

Queue Number	2877646	Transaction Date	17 Oct 2026, 12:14:19
Site Name	840 - Emirates Auctions	Transaction Number	35685318 (CC10013) (CC10011)



Vehicle Details

Chassis Number	WPOCE2A80R*****
Specification	GCC Specification
Make	Porsche
Model	S
Model Year	2024
Color	Silver
Mileage	13344 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	FRONT BOTH SIDE FIBER PAINT NOT CHECKD & RIGHT SIDE PORTION DAMAGED REPAIRED	مدكار
01.B Paint	BODY TOTALLY PROTECTION STICKER PAINT NOT CHECK,PARTS FIBER,	الصيغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COMPLETELY COVERED	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Windshield	FRONT SPOT CRACK	زجاج
01.G Bonnet	FIBER PAINT NOT CHECKD,REFITTED	غطاء المحرك
01.H Sign of front accident	FRONT ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.I Vehicle Model	718 SPYDER	طراز المركبة

02 Chassis Condition الشاسي

02.A Chassis	FRONT RIGHT SIDE CHASSIS OUTER SKIRT DEEP SCRATCHSE / CHECK VISIBLE AREA ONLY / OK	الشاسية
02.B Other	FOR FULL INSPECTION REMOVE INNER FENDER UNDER FLOOR ENGINE COVER & FRONT INNER COMPARTMENT COVER FOR RECHECK	اخرى
02.C Chassis Number	VIN CHECK ONLY DOOR POST STICKER	رقم القاعدة

03 Engine Condition المحرك

03.A Engine Visual Condition	VISUAL OK	الحالة النظرية للمحرك
------------------------------	-----------	-----------------------

Condition	Remarks	الحالة
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	VISUAL OK	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
06.B Fog light	RIGHT SIDE LOOSE	كشاف الضباب
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	HARD	ممتص الصدمات
08 Interior Condition		الحالة الداخلية
08.A AC Condition	NOT COOLING	المكيف
08.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae