CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2977299
Transaction Date	12 Nov 2026, 13:06:34
Site Name	840 - Emirates Auctions
Transaction Number	85108185 (CC10009) (CC10019)



Vehicle Details

Chassis Number	SCBCG63W5B*******
Specification	GCC Specification
Make	Bentley
Model	Continental
Model Year	2011
Color	Silver
Mileage	174485 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	12

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REPAINTED,PORTION REPAIRED,FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Doors	RIGHT SIDE REPAINTED,PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR DENT RUST PROOFED, FRONT CHASSIS COVERED	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	SHOCK NOT WORKING	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED, BOTH SIDE WHEEL ARCH DENT	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COVERED MUDDY OILY PORTION MINOR DENT, CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	REMOVE FRONT BOTH SIDE CHASSIS UNDER FLOOR FENDERS COVERS FOR RECHECK	اخري
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OIL WET PARTS REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	DRIVER SEAT SWITCH BUTTON PORTION MISSING	حالة المقاعد
05 Transmission Condition		**الجير**

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY,MINOR JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Other	SUSPENSION REFITTED	اخري
09 Interior Condition		الحاله الداخليه
09.A Other	INNER PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
09.B AC Condition	OK	المكيف
09.C Dash Board	GLOVE BOX PORTION LOOSE	لوحة القياده
09.D Sun Visor	RIGHT SIDE BRACKET DAMAGED	حاجب الشمس
09.E Steering Wheel and control buttons	WORN OUT, LOWER COVER DAMAGED LOOSE	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae