CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906084
Transaction Date	26 Oct 2026, 15:54:59
Site Name	840 - Emirates Auctions
Transaction Number	21930553 (CC10021) (CC10021)



Vehicle Details

Chassis Number	6T1BK40KX8*******
Specification	GCC Specification
Make	Toyota
Model	Aurion
Model Year	2008
Color	Silver
Mileage	321253 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN , PORTION SCRATCHES	دعامية
01.E Trunk	NOT CLOSING	صندوق
01.F Sign of front accident	BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS MUDDY GETTING RUSTY , PORTION DENT	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY , MINOR JERKING	الحالة النظريه للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2021 EXPIRED	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CRACK	مؤخرة الرودات
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
10.B Mirror	CENTER VIEW MIRROR DAMAGE	المرايا
10.C AC Condition	OK , AC GRILL DAMAGE	المكيف
10.D Roof Light	PANEL DAMAGE	أنارة السقف
10.E Dash Board	DAMAGE	لوحة القياده
10.F Sun Visor	PORTION WORN OUT	حاجب الشمس
10.G Door Panel	PORTION DAMAGE	لوحة بطانة الباب
10.H Steering Wheel and control buttons	PORTION WORN OUT , HORN NOT WORKING	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae