

Queue Number

2843814

Transaction Date

07 Oct 2026, 14:14:24

Site Name

840 - Emirates Auctions

Transaction Number

32466998 (CC10013) (CC10011)



Vehicle Details

Chassis Number	JN8AY2NY9G*****
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2016
Color	White
Mileage	125878 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE SKIRT PORTION LOOSE	مدكار
01.B Paint	MINOR DENTS SCRATCHES ON BODY,PORTION FADED GETTING RUSTY,PAINT PORTION DAMAGED TOUCH UPS	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION DIRTY MUDDY	الارضية
01.E Bumper	KIT MODIFIED,MISALIGN	دعامية
01.F Bonnet	SHOCK NOT WORKING	غطاء المحرك
01.G Trunk	REAR SWITCH DAMAGED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME DIRTY GETTING RUSTY	الشاسيه
--------------	-----------------------------------	---------

03 Engine Condition

المحرك

03.A Smoke	WHITE	دخان
03.B Engine Visual Condition	DIRTY , PARTS GETTING RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	FRONT BOTH SIDE SEATS LOOSE,REAR MIDDLE NECK REST MISSING	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	DIRTY , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B DIFFERENTIAL	FRONT OIL LEAK	الدفرنشل
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES,WHEEL HUB OUTER COVER MISSING & STUDS DAMAGED	حالة الجنوط
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING RUSTY	دسك و طنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
08.B Ball Joint	BOOT DRY CRACK	مفصل كروي
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
09.B Axle	BOOT DRY CUT	اكسلات
10 Interior Condition		الحالة الداخليه
10.A Other	INTERIOR MODIFIED PARTS REFITTED GETTING RUSTY,REAR CUP HOLDER MISSING	اخرى
10.B Mirror	LEFT SIDE MINOR LOOSE AUTO FOLDING NOT WORKING	المرايا
10.C AC Condition	OK	المكيف
10.D Dash Board	PORTION WORN OUT LOOSE	لوحة القيادة
10.E Roof Ceiling	LOOSE	بطانه السقف
10.F Sun Visor	LEFT SIDE MIRROR CASE LOOSE,RIGHT SIDE MIRROR CRACK	حاجب الشمس
10.G Door Panel	REAR RIGHT SIDE HANDLE MISSING,RIGHT SIDE B/PILLAR GRAB HANDLE LOOSE	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae