

Queue Number

2841174

Transaction Date

06 Oct 2026, 13:43:28

Site Name

840 - Emirates Auctions

Transaction Number

17736251 (CC10010) (CC10010)



Vehicle Details

Chassis Number

WDDWF4CB2F*****

Specification

GCC Specification

Make

Mercedes

Model

C 200

Model Year

2015

Color

White

Mileage

197339 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED ,REAR BOTH SIDE REPAINTED PORTION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES ,	الصبغ
01.C Doors	PORTION REPAINTED.	أبواب
01.D Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA ,	الارضية
01.F Bumper	MISALIGN ,SCRATCHES .	دعامية
01.G Bonnet	REFITTED . REPAIRED REPAINTED DENT .	غطاء المحرك
01.H Trunk	REPAINTED	صندوق
01.I Sign of front accident	FRONT ASSEMBLY REFITTED.	وجود مؤشر لحادث في المقدمة
01.J Sign of side accident	QUARTER PANEL WHEEL ARCH REPAIRED,	وجود مؤشر لحادث في الجانب
01.K Sign of back accident	BACK PANEL ,QUARTER PANEL ,COMPARTMENT FLOOR REPAIRED,DENT .	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIS COVERED MUDDY ,CHECKED ONLY VISIBLE AREA ,REAR EXTENSION END REPAIRED DENT .	الشاسيه
02.B Other	NEED TO REMOVE FENDER COVER UNDER FOR INSPECTION .	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK COMPONENT PARTS RUSTY SHAKING ,ABNORMAL NOISY .
------------------------------	--

الحالة النظرية للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY PORTION LOOSE.	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	GET JERKING COMPONENT PARTS RUSTY.	الحالة النظرية للجير
05.B Road Test	NOT CHECKED . ,	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025 DRY CRACKED .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025 DRY CRACKED .	الاطار الخلفي
06.C Rims Condition	MINOR SCRATCHES .	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LEAN FADED.,	الاضاءة الرئيسية
07.B Warning Light	EXTRA WARNING LIGHT /WARNING MESSAGE ON IN CLUSTER	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY.,	دواسة الفرامل
08.B Disc&Drum	PARTS RUSTY.	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	WEAK,	ممتص الصدمات
09.B Arms	BUSHES CRACKED .	ازرع
10 Steering Condition		المقود
10.A Steering Box	HARD	جهاز المقود
11 Interior Condition		الحالة الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED.	اخرى
11.B Mirror	CENTER MIRROR MISSING.	المرآيا
11.C AC Condition	OK	المكيف
11.D Roof Light	ASSEMBLY MISSING.	أنارة السقف
11.E Power Window Switch And Glass	NOT WORKING PROPERLY GLASS OPEN ALL SWITCH LOOSE.	مفتاح النافذه و الزجاج
11.F Roof Ceiling	PORTION LOOSE.	بطانه السقف
11.G Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.I Sunroof	FRONT GLASS PORTION CRACKED . NOT WORKING.	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae