



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Jul 2022, 13:15:40
Transaction Number	19591519 (CC10006)	Queue Number	312309



Chassis Number	WBAFR7102CC949198
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	535
Model Year	2012
Color	Silver
Mileage	119294 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK & REAR GRAIL LOOSE	المكيف
01.B Roof Ceiling	LOOSE	بطانه السقف
01.C Power Window Switch	REAR CURTAIN NOT WORKING	مفتاح النافذه
02 Transmission Condition		الجير
02.A Visual Gear Box Condition	OIL LEAK	حالة الجير النظرى
02.B Road Test	NOT CHECK	فحص علي الطريق
02.C Propeller Shaft	RUBBER CRACKED	ناقل الحركة
03 Chassis Condition		الشاصي
03.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
04 Body		جسم المركبة
04.A Floor	UNDER FLOOR COVER DAMAGED	الارضيه
04.B Fenders	REAR LEFT SIDE PORTION REPAIRED,REPAINTED	مدكار
04.C Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
04.D Trunk	HANDLE TRUNK MISSING & PORTION REPAINTED REPAIRED	صندوق

DEFECT	REMARKS	
05 Steering Condition		المقود
05.A Steering Oil	OIL LEAK	زيت المقود
06 Engine Condition		المحرك
06.A Visual Engine Condition	OIL LEAK & ABNORMAL NOISY	حالة المحرك النظري
07 Tires and Rims Condition		الاطارات
07.A Rear Tyre	BOTH SIDE 2021/2017 EXPIRED CRACKED	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.