CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2919590
Transaction Date	28 Oct 2026, 16:42:11
Site Name	840 - Emirates Auctions
Transaction Number	53574891 (CC10013) (CC10025)



Vehicle Details

Chassis Number	WP1ZZZ92ZG*******
Specification	GCC Specification
Make	Porsche
Model	Cayenne
Model Year	2016
Color	Blue
Mileage	93252 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE PORTION REPAIRED REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR BOTH SIDE & FRONT RIGHT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION COVERED DIRTY MUDDY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED REFITTED SHOCK WEACK	غطاء المحرك
01.H Trunk	REFITTED	صندوق
01.I Door Handle &Lock	FRONT BOTH SIDE SENSOR LOCK COVER MISSING	مقابض الأبواب والأقفال
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	DIRTY , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	DIRTY , PARTS GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

CAR CHECK

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Suspension System		ممتص الصدمات
06.A Arms	ARM BUSHES DRY CRACK	ازرع
06.B Ball Joint	BOOT CUT	مفصل كروي
06.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
07 Steering Condition		المقود
07.A Tie Rod End	BOOT CUT	مؤخرة الرودات
08 Interior Condition		الحاله الداخليه
08.A AC Condition	OK	المكيف
08.B Power Window Switch And Glass	FRONT RIGHT SIDE SWITCH LOOSE	مفتاح النافذه و الزجاج
08.C Sun Visor	BOTH SIDE LIGHT MIRROR NOT WORKING	حاجب الشمس
08.D Door Panel	PORTION WORN OUT , LEATHER PORTION LOOSE	لوحة بطانة الباب
08.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae