

Queue Number

2852187

Transaction Date

10 Oct 2026, 12:46:05

Site Name

840 - Emirates Auctions

Transaction Number

98179840 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JNKDV6AE8D*****
Specification	GCC Specification
Make	Infiniti
Model	G 25
Model Year	2013
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.E Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.F Bonnet	DAMAGED ,REFITTED ,MISALIGNED .FIREWALL COVER DAMAGED .	غطاء المحرك
01.G Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ,FENDER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة
01.H Sign of side accident	QUARTER PANEL WHEEL ARCH REPAIRED.	وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED BEND GETTING RUSTY.	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Mount	BUSHES CRACKED .	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY,PARTS MISSING . COMPARTMENT WIRING DAMAGED LOOSE.	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION CUT .	حالة المقاعد
---------------------	---------------	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظرية للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE EXPIRED CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE EXPIRED ,CRACKED WORN OUT .	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES ON BODY .	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED ,ALL LIGHT NOT CHECKED .	الاضاءة الرئيسية
07.B Other	FUSE BOX ASSEMBLY DAMAGED ,PARTS MISSING.	اخرى
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنايير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
10.C Axle	BOOT CUT .	اكسلات
11 Interior Condition		الحالة الداخلية
11.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخرى
11.B AC Condition	NOT CHECKED.	المكيف
11.C Dash Board	MELTED PORTION CUT ,LOOSE.	لوحة القيادة
11.D Odometer reading	NOT CHECKED.	قراءة عداد المسافات
11.E Door Panel	WORN OUT,PORTION LOOSE.	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT.	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير

station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae