CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906137
Transaction Date	29 Oct 2026, 13:23:04
Site Name	840 - Emirates Auctions
Transaction Number	90655537 (CC10010) (CC10011)



Vehicle Details

Chassis Number	4T1BG22K4W*******
Specification	Imported
Make	Toyota
Model	Camry
Model Year	1998
Color	Silver
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAIRED REPAINTED DENTS SCRATCHES , PORTION RUSTY , PORTION FADED, PAINT PORTION DAMAGED	الصبغ
01.C Doors	FRONT LEFT SIDE NOT OPEN/MISALIGNED .	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN , PORTION DAMAGED , LOGO MISSING	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Door Handle &Lock	FRONT LEFT SIDE & REAR RIGHT SIDE OUTER HANDLE DAMAGED MISSING	مقابض الأبواب والأقفال
01.I Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.J Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASSIS REPAIRED DENT GETTING RUSTY.	الشاسيه
02.B Chassis Number	VIN CHECKED ONLY WINDSHIELD /.	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2026 , LEFT SIDE NO AIR	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED , ALL LIGHT NOT WORKING	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER PORTION DAMAGED / INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
10.B Mirror	CENTER MIRROR MISSING	المرايا
10.C AC Condition	NOT CHECK	المكيف
10.D Power Window Switch And Glass	REAR BOTH SIDE PART MISSING	مفتاح النافذه و الزجاج
10.E Audio	LCD PORTION CRACK	صوتيات
10.F Dash Board	PORTION CRACK	لوحة القياده
10.G Roof Ceiling	LOOSE	بطانه السقف
10.H Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.I Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.J Gear Shifting Lever	KNOB WORN OUT , DUST COVER DAMAGED MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير

station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae