

Queue Number

2869107

Transaction Date

16 Oct 2026, 12:26:59

Site Name

840 - Emirates Auctions

Transaction Number

13307532 (CC10010) (CC10010)



Vehicle Details

Chassis Number	1N4BL4CV1K*****
Specification	Imported
Make	Nissan
Model	Altima
Model Year	2019
Color	Grey
Mileage	193692 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT & REAR BOTH SIDE REPAINTED PORTION REPAIRED FRONT REFITTED .	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	REAR LEFT SIDE ,FRONT RIGHT SIDE REPAINTED PORTION REPAIRED.	أبواب
01.D Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED REFITTED .	غطاء المحرك
01.H Pillars	LEFT SIDE C/PILLAR ROCKER PANEL ,QUARTER PANEL REPAIRED.	القوائم
01.I Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ,FENDER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة
01.J Sign of side accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ,FENDER FRAME REPAIRED.	وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIS REPAIRED DENT . COMPLETE COVERED ,CHECKED ONLY VISIBLE AREA .	الشاسيه
02.B Other	REMOVE FENDER COVER UNDER COVER FOR INSPECTION .	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY,SOME MOUNT BOLT NOT FIX PROPERLY .	الحالة النظرية للمحرك
------------------------------	---	-----------------------

Condition	Remarks	الحالة
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	PARTS REFITTED GET JERKING ,COMPONENT PARTS GETTING RUSTY.	الحالة النظرية للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 CRACKED WORN OUT .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024 CRACKED WORN OUT .	الاطار الخلفي
05.C Rims Condition	MINOR DENTS SCRATCHES .	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	BRACKET DAMAGED . MISALIGNED .	الاضاءة الرئيسية
06.B Warning Light	EXTRA WARNING LIGHT /WARNING MESSAGE ON IN CLUSTER,	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY .	دواسة الفرامل
07.B Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK ,WEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED .	ازرع
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخرى
09.B AC Condition	LOW COOLING.	المكيف
09.C Dash Board	REPAIRED ,LEATEHR REPLACED .	لوحة القيادة
09.D Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
09.E Air Bag	DAMAGED .	وسائد هوائية
09.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae