




TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	22 Jul 2022, 12:02:30
Transaction Number	24257116 (CC10006)	Queue Number	312309



Chassis Number	WAUZZZFFXLA053944
Engine Number	
Vehicle Class	Car
Manufacturer	Audi
Model	A3
Model Year	2020
Color	Black
Mileage	73174 Km
Fuel Type	Petrol
No. Of Cylinders	3
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Floor	UNDER FLOOR,COVERED,MUDDY, FOR RECHECK PROPERLY REMOVE COVERE & WASH MUDDY	الارضية
01.B Paint	BODY MINOR DENT ,SCRATCHES	الصبغ
02 Transmission Condition		الجير
02.A Visual Gear Box Condition	OK	حالة الجير النظرى
02.B Road Test	NOT CHECK	فحص علي الطريق
02.C Gear Box Mount	MOUNT BUSH CRACKED	كرسي الجير
03 Engine Condition		المحرك
03.A Other	ENGINE HOUSE MUDDY	اخرى
03.B Visual Engine Condition	SHAKING	حالة المحرك النظرى
03.C Mount	MOUNT BUSH CRACKED	كرسي
04 Interior Condition		الحاله الداخليه
04.A AC Condition	OK	المكيف
05 Tires and Rims Condition		الاطارات

DEFECT	REMARKS	
05.A Front Tyre	BOTH SIDE 2021 CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021 CRACKED	الاطار الخلفي
05.C Rims Condition	RIMS HAVE MINOR DENT SCRATCHES	حالة الجنوط
06 Suspension System		ممتص الصدمات
06.A Ball Joint	BOOT CRACKED	مفصل كروي
06.B Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
07 Steering Condition		المقود
07.A Tie Rod End	BOOT CRACKED	مؤخرة الرودادات
08 Chassis Condition		الشاسي
08.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.