CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2986985
Transaction Date	16 Nov 2026, 16:52:32
Site Name	840 - Emirates Auctions
Transaction Number	24033229 (CC10013) (CC10011)



Vehicle Details

Chassis Number	JTFLJ73J07*******
Specification	GCC Specification
Make	Toyota
Model	Land Cruiser
Model Year	2007
Color	Black
Mileage	156508 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION STICKER,PORTION RUSTY,PAINT PORTION CRACKED	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR BODY MOUNT REFITTED , FLOOR EXTRA PARTS FITTING PORTION REPAIRED MODIFIED	الارضية
01.D Bumper	PART MISSING,REAR MODIFIED WITH EXTRA FITTING	دعامية
01.E Bonnet	REFITTED	غطاء المحرك
01.F Pillars	REPAIRED	القوائم
01.G Trunk	CABIN MODIFIED WITH EXTRA ACCESSORIES	صندوق
01.H Vehicle Color	BEIGE	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME RUST PROOFED REPAIRED EXTRA FITTING EXTENDED PORTION DENT GETTING RUSTY	الشاسيه
02.B Chassis Number	VIN AREA RUST PROOFED	رقم القاعدة
03 Engine Condition		المحرك
03.A Mount	MOUNT RUBBER DRY CRACK	كرسي
03.B Engine Visual Condition	OIL PAN DENT , REFITTED , MUDDY , DIRTY , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	EXTRA COVER	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Modification	EXHAUST SYSTEM MODIFIED	تعديلات
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	REFITTED , OIL SWEATING , PARTS GETTING RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
08 Suspension System		ممتص الصدمات
08.A Leaf Spring	MISALIGN BUSHES DRY CRACK	
08.B Arms	ARM BUSHES MINOR DRY CRACK	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY MODIFIED	اخري
09.B AC Condition	OK	المكيف
09.C Door Panel	PORTION LOOSE REFITTED	لوحة بطانة الباب
09.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae