



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	09 Aug 2022, 18:06:53
Transaction Number	37669067 (CC10006)	Queue Number	312309



Chassis Number	3VWJX7AT5CM647249
Engine Number	
Vehicle Class	Car
Manufacturer	Volkswagen
Model	Beetle
Model Year	2012
Color	Silver
Mileage	219235 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	USA Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Trunk	SHOCK WEAK & PORTION REPAIRED REPAINTED	صندوق
01.B Doors	RIGHT SIDE BOTH REPAIRED, REPAINTED	أبواب
01.C Fenders	FRONT BOTH SIDE , REAR RIGHT SIDE REPAIRED, REPAINTED	مدكار
01.D Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.E Bonnet	PORTION REPAIRED,REPAINTED & NOT OPEN FOR CHECK, CABLE DAMAGED	غطاء المحرك
01.F Sign of front accident		وجود مؤشر لحادث في المقدمة
02 Engine Condition		المحرك
02.A Visual Engine Condition	REFITTED & OIL WET	حالة المحرك النظري
03 Transmission Condition		الجير
03.A Visual Gear Box Condition	OIL LEAK & REFITTED	حالة الجير النظري
03.B Gear Box Mount	BUSHES CRACKED	كرسي الجير
03.C Road Test	NOT CHECK	فحص علي الطريق
04 Interior Condition		الحاله الداخليه

DEFECT	REMARKS	
04.A Roof Ceiling	LOOSE	بطانه السقف
04.B Sunroof	NOT WORKING & CURTAIN DAMAGED	فتحت سقف
04.C AC Condition	OK	المكيف
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
06 Chassis Condition		الشاسي
06.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CRACKE	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.