



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	15 Jan 2023, 17:00:43
Transaction Number	36605886 (CC10006)	Queue Number	657293



Chassis Number	KMHD741C3LU026422
Engine Number	
Vehicle Class	Car
Manufacturer	Hyundai
Model	Elantra
Model Year	2020
Color	Silver
Mileage	110176 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
02 Body		جسم المركبة
02.A Floor	UNDER FLOOR COVERED ,CHECKED ONLY VISIBLE AREA .	الارضيه
02.B Rusty	UNDER BDY ,SUSPENSION PARTS GETING RUSTY .	صدأ
02.C Paint	BODY PORTION REPAIRED ,REPAINTED .MINOR DENTS SCRATCHES .	الصبغ
02.D Fenders	REPAIRED ,REFITTED.	مدكار
02.E Bumper	MISALIGNED. SCRATCHES.	دعامية
03 Engine Condition		المحرك
03.A Visual Engine Condition	MINOR OIL LEAK .	حالة المحرك النظرى
04 Transmission Condition		الجير
04.A Visual Gear Box Condition	OK	حالة الجير النظرى
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Chassis Condition		الشاصي

DEFECT	REMARKS	
05.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2017/2019 EXPIRED ,CRACKED .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2019 CRACKED.	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.