CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899702
Transaction Date	28 Oct 2026, 14:59:34
Site Name	840 - Emirates Auctions
Transaction Number	64842161 (CC10010) (CC10010)



Vehicle Details

Chassis Number	55SWF4KB3J*******
Specification	Imported
Make	Mercedes
Model	C 300
Model Year	2018
Color	White
Mileage	91521 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT & REAR BOTH SIDE REPAINTED FRONT REFITTED .	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES ,	الصبغ
01.C Doors	REAR RIGHT SIDE DOOR REPAINTED.	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	MISALIGN SCRATCHES,	دعامية
01.G Windshield	FRONT SPOT CRACKED.	زجاج
01.H Trunk	REPAIRED REPAINTED	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME ,BULKHEAD REPAIRED ASSEMBLY REFITTED .	وجود مؤشر لحادث في المقدمة
01.J Sign of back accident	BACK PANEL REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COMPLETE COVERED CHECKED ONLY VISIBLE AREA ,END PORTION MINOR DENT ,,	الشاسيه
02.B Other	NEED TO REMOVE FENDER INNNER COVER UNDER COVER FOR INSPECTION .	اخري
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	COMPONENT PARTS REFITTED ABNORMAL NOISY ,OIL LEAK ,PARTS RUSTY.	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	GET JERKING ,COMPONENT PARTS RUSTY,	الحالة النظريه للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024 CRACKED .	الاطار الخلفي
05.C Rims Condition	MINOR DENTS SCRATCHES .	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED.	الاضاءة الرئيسية
06.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER.	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY	دواسة الفرامل
07.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	MINOR LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED.	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY.	اخري
09.B AC Condition	OK	المكيف
09.C Air Bag	OPEN REFITTED .	وسائد هوائية
09.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae