

Queue Number 2809924

Transaction Date 29 Sep 2026, 16:41:23

Site Name
840 - Emirates AuctionsTransaction Number
11809971 (CC10009) (CC10012)

Vehicle Details

Chassis Number	W1K3G5BB1M*****
Specification	GCC Specification
Make	Mercedes
Model	A 35
Model Year	2021
Color	Grey
Mileage	181452 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	LEFT SIDE BOTH REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS NOT VISIBLE	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Roof	LEFT SIDE SKIRT PORTION LOOSE	السقف
01.H Trunk	MINOR MISALIGN	صندوق

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	REMOVE ALL UNDER COVERS FOR RECHECK PROPERLY	اخرى

03 Engine Condition المحرك

03.A Engine Visual Condition	OIL LEAK PARTS REFITTED, SHAKING GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	FRONT RIGHT SIDE MINOR CUT	حالة المقاعد
---------------------	----------------------------	--------------

05 Transmission Condition الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OIL WET PARTS REFITTED MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
07 Interior Condition		الحالة الداخلية
07.A Other	INTERIOR PARTS GETTING RUSTY , (WATER FLOODED)	اخرى
07.B AC Condition	OK	المكيف
07.C Sunroof	NOT WORKING PROPERLY	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae