CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2966848
Transaction Date	09 Nov 2026, 15:39:46

Site Name
840 - Emirates Auctions

Transaction Number
19685867 (CC10013) (CC10013)



Vehicle Details

Chassis Number	3N1AB8DV9L*******
Specification	Imported
Make	Nissan
Model	Sentra
Model Year	2020
Color	Grey
Mileage	74149 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS , SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY , RUST PROOFED	الارضية
01.D Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.E Trunk	NOT OPEN	صندوق
01.F Fuel Tank	DENT	خزان الوقود
01.G Sign of front accident	FRONT BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
01.H Sign of back accident	QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT LEFT SIDE CHASSIS REPAIRED DENT GETTING RUSTY	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY KEY MISSING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT CRACK	حالة المقاعد
05 Exhaust System		نظام العادم

Condition	Remarks	الحالة
05.A Other	DENT	اخري
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	2023 DRY CRACK	الاطار الامامي
07.B Rear Tyre	2023 DRY CRACK	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Disc&Drum	MINOR DENT SCRATCHES	دسك وطنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	LEAK	ممتص الصدمات
10.B Other	ALL BUSHES DRY CRACK CUT	اخري
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED	اخري
11.B AC Condition	NOT CHECKED	المكيف
11.C Dash Board	GETTING FADED PORTION WORN OUT CRACK	لوحة القياده
11.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
11.E Sun Visor	GETTING LOOSE	حاجب الشمس
11.F Odometer reading	NOT CHECKED	قراءة عداد المسافات
11.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae