CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2944979
Transaction Date	06 Nov 2026, 16:18:25
Site Name	840 - Emirates Auctions
Transaction Number	92124881 (CC10026) (CC10026)



Vehicle Details

Chassis Number	1GYFZFR44L*******
Specification	Imported
Make	Cadillac
Model	XT 4
Model Year	2020
Color	White
Mileage	138076 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT LEFT SIDE & REAR RIGHT SIDE REPAINTED PORTION REPAIRED , FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR BOTH SIDE & FRONT LEFT SIDE REPAINTED PORTION REPAIRED & FRONT RIGHT SIDE REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DENT	الارضية
01.F Bumper	MISALIGN , FRONT LEFT SIDE REFLECTOR DAMAGE	دعامية
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COVER , CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير

Condition	Remarks	الحالة
05.B Propeller Shaft	MISSING	ناقل الحركة
05.C Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Interior Condition		الحاله الداخليه
08.A AC Condition	OK	المكيف
08.B Dash Board	WORN OUT	لوحة القياده
08.C Roof Ceiling	PORTION WORN OUT	بطانه السقف
08.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.E Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
08.F Gear Shifting Lever	KNOB PORTION CRACK	ذراع نقل السرعات
08.G Engine Start Button	REMOTE PORTION WORN OUT	زر تشغيل المحرك
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae