

Queue Number

2869076

Transaction Date

14 Oct 2026, 16:55:34

Site Name

840 - Emirates Auctions

Transaction Number

58462829 (CC10026) (CC10026)



Vehicle Details

Chassis Number	JTNGE52M4F*****
Specification	GCC Specification
Make	Toyota
Model	Previa
Model Year	2015
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED & FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR BOTH SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY SIGN OF FLOODED	صدأ
01.E Floor	UNDER FLOOR PARTS & RUNNING BOARD DENT , MUDDY	الارضية
01.F Bumper	MISALIGN PORTION DAMAGE FIX BY SCREW	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED , MISALIGN	غطاء المحرك
01.H Trunk	REPAINTED PORTION REPAIRED , NOT OPENING	صندوق
01.I Sign of back accident	BACK PANEL , BUMPER FRAME REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS GETTING RUSTY , MUDDY	الشاسيه
--------------	-------------------------------	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT STARTING , ALL SYSTEM NOT CHECK , PARTS GETTING RUSTY , SIGN OF OIL WET	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGE	حالة المقاعد
---------------------	----------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECK , PARTS GETTING RUSTY , SIGN OF OIL WET	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACK WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED , ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07.B Fog light	LENS GETTING FADED	كشاف الضباب
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	REAR SHOCK LEAKING	ممتص الصدمات
09.B Arms	BUSHES CRACK	ازرع
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE PANEL WORN OUT, INTERIOR PARTS GETTING RUSTY	اخرى
11.B Mirror	SIDE VIEW MIRROR GETTING FADED	المرآيا
11.C AC Condition	NOT CHECK	المكيف
11.D Power Window Switch And Glass	MAIN SWICTH PANEL DAMAGE	مفتاح النافذه و الزجاج
11.E Floor Matting	DIRTY	فرش الأرضيه
11.F Dash Board	PORTION WORN CRACK	لوحة القيادة
11.G Roof Ceiling	PORTION LOOSE	بطانه السقف
11.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
12 Engine Cooling System		نظام تبريد المحرك
12.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae