

Queue Number 2792892

Transaction Date 24 Sep 2026, 15:38:28

Site Name
840 - Emirates AuctionsTransaction Number
28930606 (CC10010) (CC10011)

Vehicle Details

Chassis Number	WBAKU6A08K*****
Specification	GCC Specification
Make	BMW
Model	X6
Model Year	0
Color	Unknown
Mileage	73796 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE FIBER PAINT NOT CHECK,REAR RIGHT SIDE PORTION REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED,MINOR DENTS SCRATCHES	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY .	صدأ
01.D Floor	UNDER FLOOR CHASSIS COVERED NOT VISIBLE ,CHECKED ONLY VISIBLE AREA.	الارضية
01.E Trunk	LOGO DAMAGED	صندوق
01.F Vehicle Color	BLACK .	لون المركبة
01.G Vehicle Year Model	2019	سنة صنع المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETE COVERED ,CHECKED ONLY VISIBLE AREA OK.	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	SIGN OF OIL WET , UNDER PORTION COVERED,	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	SIGN OF OIL WET , UNDER PORTION COVERED,	الحالة النظرية للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2021 CRACKED EXPIRED	الاطار الامامي
-----------------	--------------------------------	----------------

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2021 CRACKED EXPIRED	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
07 Interior Condition		الحالة الداخليه
07.A AC Condition	OK	المكيف
07.B Power Window Switch And Glass	REAR BOTH SIDE CURTAIN HANDLE PORTION DAMAGED	مفتاح النافذه و الزجاج
07.C Dash Board	LEATHER PORTION LOOSE	لوحة القيادة
07.D Roof Ceiling	PORTION LOOSE	بطانه السقف
07.E Door Panel	PORTION MELTED,LEATHER PORTION LOOSE	لوحة بطانة الباب
07.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
07.G Gear Shifting Lever	KNOB GETTING WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae