





Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18530808	Plate Category	: PRIVATE
Transaction Date	: 14 NOV 2019 13:33:36	Plate Number	: 0218 EA
Queue Number	: 118661	Import Doc. Ref.	:
Chassis Number	: JN8FY15Y92X450218	Manufacturer/Model	: NISSAN/PATROL
Engine Number	:	Model Year	: 2002
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: GOLDEN
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.03 - Steering Wheel, Change, Repair		مقبض عجلة القيادة
02.14 - Springs And Shackle Pins		الزميزك الورقي
02.16 - Engine Mounting		كراسي المحرك
02.17 - Gear Box Mounting		كراسي ناقل الحركة
03 Brake System		نظام الفرامل
03.05 - Brake Pedal		نواصة الفرامل
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.07 - Rims		الرنجات
05 Body		الهيكل
05.01 - Rusty		الصدأ
05.03 - Doors		الابواب
05.05 - Bumpers		الدعامية
05.06 - Roof		السقف
05.07 - Floor		الارضية
05.08 - Chassis (Frame)		الشاصية
05.10 - All Glasses		الزجاج الجانبي وزجاج الابواب
05.11 - Tinted Glasses		الزجاج الملون
05.12 - Side Safety Frame		الواقيات الجانبية
06 General Items		الاشياء العامة



Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18530808	Plate Category	: PRIVATE
Transaction Date	: 14 NOV 2019 13:33:36	Plate Number	: 0218 EA
Queue Number	: 118661	Import Doc. Ref.	:
Chassis Number	: JN8FY15Y92X450218	Manufacturer/Model	: NISSAN/PATROL
Engine Number	:	Model Year	: 2002
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: GOLDEN
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

06.12 - Seats Condition And Seats Fixing	R/H FRONT SEAT ADJUST SWITCHES MISSING&SYST.DEFECTIVE&TRIM PARTLY TORN	المقاعد وحالتها وتثبيتها
06.14 - Transmission Condition	INITIAL SLIGHT SHIFT SHOCK	حالة ناقل الحركة
09 Auction		الفحص الكامل
09.11 - Gear Box Oil Leaking	FRONT DIFFERENTIAL OIL LEAK	تهريب زيت الجير
09.18 - A/C Not Cooling	BLOWER NOISE	عطل في المكيف
09.21 - Body/Bumper Modified	REAR BUMPER FRAME RUSTY CORRODED&HOLE	تعديل في جسم المركبة أو الدعاميات
09.25 - Body Repainted	BODY REPAINTED	أثر صيغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only.		

Test Certificate



Transfer Certificate : 53451528
 Chassis No : JN8FY15Y92X450218
 Vehicle Make : NISSAN.
 Vehicle Model : PATROL
 Vehicle Class : Light Vehicle
 Body Type : STATION
 Fuel : Benzene
 Color : Golden
 Drive Direction : --
 Dimensions : (H x W x L) -- x -- x --
 Current Odometer : 293070 Kms.
 Origin : Japan
 Gear Type : --
 Engine No : TB4B006611
 Axles No : 2
 No Of Doors : 5
 G. V. W. : 3000 Kgs.
 Model Year : 2002
 Engine Size : 4800 CC
 Horse Power : --
 Cylinders : 6
 No Of Seats : 7
 Empty Weight : 2325 Kgs.

Certificate Number : 5-TAS-2019-11118280
 Inspection Date : 14-11-2019
 Certificate Print Date : 14-11-2019
 Services : Registration Test
 Vehicle Testing Partner : Tasjeel
 Vehicle Testing Center : Tasjeel Al Aweer
 Total Time Taken : 24 min 42 sec
 Appointment Ref Number : --
 Start Time : 18:51
 End Time : 19:16
 Lane : 03
 Token No. : 155
 Attempt : 1
 Prints No : 1

Parameter Readings

Service brake imbalance on front axle 2 %	Service brake imbalance on rear axle 7 %	Parking brake imbalance between LHS and RHS 15 %	Vehicle on Petrol CO Reading 0.1 %
Vehicle on Petrol HC Reading 36 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Vehicle Floor REPAIR OR REPLACE REAR CROSS MEMBER RUSTY HOLE	Others (Major)	Major
Tinted REMOVE ALL DOOR GLASSES TINT	Reflective	Major

Discrepancies

	Old Value	New Value	Verified
Doors and Locks Incorrect Number of doors (does not require doc)	5	4	
Vehicle Make - Registration Incorrect Make - Does Not Require Document	NISSAN.	NISSAN	
Vehicle Model - Registration Incorrect Model - Does Not Require Document	PATROL	PATROL	

Inspection Remarks:

BULK HEAD , FENDER FRAME REPAIRED , FRONT LEFT SIDE DOOR PILLER & DOOR PILLER POST REPAIRED , UNDER BODY CHASSIS & SUSPENSION PARTS RUSTY