

06.A AC Condition

TEST CERTIFICATE

المكيف

Site Number 840-Emirates Auctions Transaction Date 03 Oct 2021, 18:07:51

Transaction Number **31835592 (CC10006)** Queue Number **312309**



Chassis Number **SALVA2BG4GH098348**

Engine Number

Vehicle Class Car

Manufacturer Range Rover

Model Vogue

Model Year 2016

Color Black

Mileage O N/A

REMARKS	
	جسم المركبة
BODY PORTION REPAIRED & REPAINTED	الصبغ
REAR LEFT DOOR REPAINTED,REFITIED&FRONT RIGHT REPAINTED	أبواب
UNDER BODY FULLY COVERD	الارضية
FRONT FENDER FIBER	مدكار
BONNET REPAIRED, REPAINTED, REFITIED	غطاء المحرك
FRONT CRASH BOX BUMPER FRAME REPAIRED	اخري
	الشاصي
VISABLE AREA OK	الشاسيه
	الاضاءة
OK	الاضاءة الرئيسية
	المقاعد
ОК	اخري
	الاطارات
BOTH 2020	الاطار الامامي
BOTH 2020	الاطار الخلفي
	الاجزاء الداخلية
	BODY PORTION REPAIRED & REPAINTED REAR LEFT DOOR REPAINTED, REFITIED& FRONT RIGHT REPAINTED UNDER BODY FULLY COVERD FRONT FENDER FIBER BONNET REPAIRED, REPAINTED, REFITIED FRONT CRASH BOX BUMPER FRAME REPAIRED VISABLE AREA OK OK OK

ОК

DEFECT	REMARKS	
06.B Mirror	ОК	المرايا
07 Engine Condition		المحرك
07.A Other	OK	اخري
08 Transmission Condition		الجير
08.A Gear Box	OK	الجير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا
 تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من