

Queue Number 2822507

Transaction Date 02 Oct 2026, 16:55:47

Site Name
840 - Emirates AuctionsTransaction Number
39590252 (CC10013) (CC10011)

Vehicle Details

Chassis Number 6G1MZ55H49*****
 Specification GCC Specification
 Make Chevrolet
 Model Caprice
 Model Year 2009
 Color White
 Mileage 298712 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED, MINOR DENT SCRATCHES, PORTION RUSTY	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DENT	الارضية
01.F Bumper	PORTION CRACK	دعامية
01.G Bonnet	SHOCK MISSING , REFITTED	غطاء المحرك
01.H Pillars	LEFT SIDE ROCKER PANEL COVER MISSING	القوائم
01.I Trunk	REFITTED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS PORTION GETTING RUSTY / CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Other	UPPER COVER MISSING	اخرى
03.B Engine Visual Condition	NOT START ALL SYSTEM NOT CHECK , REFITTED , PARTS GETTING RUSTY , MODIFIED	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED / REAR LCD FADED	حالة المقاعد
---------------------	----------------------------------	--------------

Condition	Remarks	الحالة
05 Exhaust System		نظام العادم
05.A Catalytic Converter	CUT REWELDED NOISY	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	NOT CHECK , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
06.B Propeller Shaft	MIDDLE RUBBER CRACK	ناقل الحركة
06.C Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	2024 DRY CRACK	الاطار الامامي
07.B Rear Tyre	2024 DRY CRACK	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	LENS FADED ALL LIGHT NOT CHECKED	الاضاءة الرئيسية
08.B Tail Light	PORTION CRACK	الضوء الخلفي
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES DRY CRACK	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
11 Interior Condition		الحالة الداخليه
11.A Other	INTERIOR PARTS DIRTY GETTING RUSTY / CENTER CONSOLE BOX PORTION WORN OUT	اخرى
11.B AC Condition	NOT CHECKED	المكيف
11.C Power Window Switch And Glass	SWITCH PANEL DAMAGED	مفتاح النافذه و الزجاج
11.D Audio	SCREEN FADED / ANTINNA MISSNG	صوتيات
11.E Dash Board	GETTING FADED / GLOVE BOX LOCK DAMAGED	لوحة القيادة
11.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae