



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>27 May 2023, 11:21:20</b>
Transaction Number	<b>42769279 (CC10013)</b>	Queue Number	<b>727433</b>



Chassis Number	<b>JHLRE48517C415274</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Honda</b>
Model	<b>CRV</b>
Model Year	<b>2007</b>
Color	<b>Black</b>
Mileage	<b>485296 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	NOT WORKING & SWITCH DAMAGED	المكيف
01.B Mirror	RIGHT SIDE PORTION DAMAGED	المرايا
<b>02 Steering Condition</b>		<b>المقود</b>
02.A Steering Oil	OIL LEAK	زيت المقود
02.B Steering Boot	BOOT LEAK	ربلة المقود
02.C Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Propeller Shaft	REAR MISSING	ناقل الحركة
03.B Visual Gear Box Condition	JERKING OIL LEAK & WET	حالة الجير النظرى
<b>04 Body</b>		<b>جسم المركبة</b>
04.A Floor	UNDER FLOOR PORTION COVER & MISALIGN MINOR DENT	الارضيه
04.B Bumper	DAMAGED	دعامية
04.C Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCARTCHES & PORTION FADED ,PORTION RUSTY	الصبغ
04.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ

DEFECT	REMARKS	
04.E Trunk	DAMAGED	صندوق
04.F Sign of back accident		وجود مؤشر لحادث في الخلف
<b>05 Exhaust System</b>		<b>نظام العادم</b>
05.A Other	DENT	اخرى
<b>06 Engine Condition</b>		<b>المحرك</b>
06.A Visual Engine Condition	OIL LEAK & WET	حالة المحرك النظري
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	CHASSIS MUDDY & OILY CHECK VISIBLE AREA ONLY/OK	الشاسيه
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Head Light	LENS FADED	الاضاءة الرئيسية
08.B Tail Light	BOTH SIDE CRACKED	الانارة
<b>09 Suspension System</b>		<b>ممتص الصدمات</b>
09.A Arms	LOWER ARM BUSH CRACK	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.