CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2998740
Transaction Date	17 Nov 2026, 14:04:32
Site Name	840 - Emirates Auctions
Transaction Number	40889277 (CC10009) (CC10019)



Vehicle Details

Chassis Number	1GNKV8KD4E*******
Specification	GCC Specification
Make	Chevrolet
Model	Traverse
Model Year	2014
Color	Gold
Mileage	113269 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE & REAR BOTH SIDE REPAINTED,PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED	الصبغ
01.C Doors	REAR LEFT SIDE REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR MUDDY PORTION MINOR DENT	الارضية
01.F Bumper	MISALIGN	دعامية
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED MUDDY CHECKED VISIBLE AREA OK	الشاسيه
02.B Chassis Number	STICKER FADED	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	MINOR OIL LEAK REFITTED SHAKING GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	FRONT RIGHT SIDE SEAT SIDE COVER PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL LEAK REFITTED	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Lights		الاضاءة
06.A Head Light	RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
06.B Tail Light	BOTH SIDE DAMAGED	الضوء الخلفي
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
08 Interior Condition		الحاله الداخليه
08.A Other	INETRIOR PARTS GETTING RUSTY	اخري
08.B Mirror	SWITCH LOOSE	المرايا
08.C AC Condition	OK	المكيف
08.D Sun Visor	RIGHT SIDE COVER MIRROR MISSING	حاجب الشمس
08.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae