



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	23 Mar 2022, 12:04:31
Transaction Number	99631064 (CC10008)	Queue Number	312309



Chassis Number	JMYHNP13W7A700489
Engine Number	
Vehicle Class	Heavy
Manufacturer	Mitsubishi
Model	L 300
Model Year	2007
Color	White
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Odometer reading	ODOMETER NOT CHECKED	قراءة عداد المسافات
01.B AC Condition	NOT CHECKED	المكيف
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2014/ EXPIRED	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2014. EXPIRED	الاطار الخلفي
03 Engine Condition		المحرك
03.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK , REFITTED ,OIL LEAK	حالة المحرك النظري
04 Suspension System		ممتص الصدمات
04.A Arms	LOWER ARM BUSHES CRACKED	ازرع
04.B Leaf Spring	BUSHES WORN OUT	
04.C Ball Joint	BOOT CUT	مفصل كروي
05 Steering Condition		المقود
05.A Steering Boot	BOOT CRACKED	ربلة المقود
05.B Axle	BOOT CRACKED	اكسلات

DEFECT	REMARKS	
05.C Steering Oil	SIGN OF MINOR OIL LEAK	زيت المقود
06 Body		
06.A Paint	BODY REPAINTED PORTION REPAIRED , RUSTY , MINOR DENTS SCRATCHES ON BODY	الصبغ
06.B Floor	UNDER FLOOR PARTS RUSTY ,FLOOR RUSTY HOLES	الارضية
06.C Fuel Tank	DENT	خزان الوقود
06.D Roof	ROOF & ROOF RAILL BODY PORTION HAVE RUSTY HOLES	السقف
07 Transmission Condition		
07.A Visual Gear Box Condition	REFITTED , OIL LEAK	حالة الجير النظرى
07.B Road Test	NOT CHECKED	فحص علي الطريق
07.C Gear Box Mount	RUBBER CRACKED	كرسي الجير
07.D Propeller Shaft	DAMAGED	ناقل الحركة
08 Seats Condition		
08.A Seat Belt	FRONT RIGHT SIDE NOT WORKING	حزام الأمان
09 Chassis Condition		
09.A Chassis	RUST PROOFED, STILL GETTING RUSTY	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.