



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20962816	Plate Category	: PRIVATE
Transaction Date	: 06 SEP 2020 09:49:55	Plate Number	: 675 EA
Queue Number	: 216462	Import Doc. Ref.	:
Chassis Number	: WDDGF8FB4CA637675	Manufacturer/Model	: MERCEDES/C250
Engine Number	:	Model Year	: 2012
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.13 - Stub Axle Assemblies, Boots		المحور
		FRONT RIGHT AXLE BOOTS SLIGHT CRACKS
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
		SUSPENSION BUSHES & BOOTS SLIGHT CRACK
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
		BRAKE ROTORS RUSTY/ REAR BRAKE PADS ALMOST WORN OUT
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		FRONT TIRES DOT 2018/ REAR TIRES DOT 2018 & 2019
04.07 - Rims		الرنجات
		SCRATCHES
05 Body		الهيكل
05.02 - Paint		الصيغ
		BODY SCRATCHES & DENTS
05.08 - Chassis (Frame)		الشاصية
		FRONT RIGHT SIDE MEMBER END REPAIRED/ UPPER SKIRT DENT
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي
		FRONT WINDSHIELD REPLACED
06 General Items		الاشياء العامة
06.02 - Wiper Arms		أذرع ماسحات الزجاج
		RIGHT WIPER MALFUNCTION
06.10 - Mirrors Side View		المرآيا الجانبية
		MALFUNCTION
06.13 - Exhaust System		نظام العادم
		REWELDED
06.14 - Transmission Condition		حالة ناقل الحركة
		OK
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
		OIL LEAK
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		165535 KMS
09 Auction		الفحص الكامل



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20962816	Plate Category	: PRIVATE
Transaction Date	: 06 SEP 2020 09:49:55	Plate Number	: 675 EA
Queue Number	: 216462	Import Doc. Ref.	:
Chassis Number	: WDDGF8FB4CA637675	Manufacturer/Model	: MERCEDES/C250
Engine Number	:	Model Year	: 2012
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.02 - Need Wheel Alignment		يحتاج الى ميزانية العجلات
09.14 - Sign Of Front Accident	FENDER FRAME/ BULKHEAD/ RADIATOR SUPPORT REPAIRED / FENDERS & BONNET REFITTED	أثر حادث في مقدمة المركبة
09.15 - Sign Of Rear Accident	BACK PANEL DENT	أثر حادث في مؤخرة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.24 - Digital Display Damaged/Warning Lights	TYRE PRESSURE/ FRONT RIGHT SIDE MARKER LIGHT FAULTY MESSAGES ON	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صيغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.		
شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسؤولة عن العيوب الخفية		

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	WDDGF8FB4CA637675
Vehicle Make :	MERCEDES
Vehicle Model :	C250
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	165538 Kms.
Origin :	Germany
Model Year :	2012
Gear Type :	--
Engine Size :	4700 CC
Engine No :	NIL
Horse Power :	208
Axles No :	2
Cylinders :	6
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 1545 Kgs. 2000 Kgs.

Certificate Number :	5-TAS-2020-12514517
Inspection Date :	09-09-2020
Certificate Print Date :	09-09-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	29 min 5 sec
Appointment Ref Number :	--
Start Time :	14:55
End Time :	15:24
Lane :	01
Token No. :	8
Attempt :	1
Prints No :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

15048 KM	1549 L	2510 AED	3.8 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 20 %	Service brake imbalance on rear axle 17 %	Parking brake imbalance between LHS and RHS 17 %	Vehicle on Petrol CO Reading 0.5 %
---	--	---	---------------------------------------

Vehicle on Petrol HC Reading

201 PPM VOL

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	4700	2500	

Inspection Remarks:

FRONT RIGHT SIDE MEMBER END REPAIRED/ UPPER SKIRT DENT/FENDER FRAME/ BULKHEAD/ RADIATOR SUPPORT REPAIRED / FENDERS & BONNET REFITTED

Payment Details

Inspection Performed by 59460	Payment Method VTP Credit Account	Transaction Number 12514517	Service Fees AED 170 Collected on 09/09/2020
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Raul Canceran Galang

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

