

Queue Number	2783718	Transaction Date	21 Sep 2026, 13:48:57
Site Name	840 - Emirates Auctions	Transaction Number	93492064 (CC10010) (CC10010)



Vehicle Details

Chassis Number	WVGWP2AU7J*****
Specification	GCC Specification
Make	Volkswagen
Model	Golf R
Model Year	2018
Color	White
Mileage	225846 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE & REAR RIGHT SIDE REPAINTED PORTION REPAIRED , FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY TOTALLY PROTECTION STICKER PAINT NOT CHECK PROPERLY , PORTION REPAIRED REPAINTED , PORTION GETTING FADED	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Bonnet	REFITTED	غطاء المحرك
01.E Trunk	REFITTED , MISALIGN	صندوق
01.F Sign of front accident	FRONT ASSEMBLY REFITTED .	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS COMPLETE COVERED PORTION MUDDY ,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED GETTING RUSTY , SIGN OF OIL WET , SHAKING,ABNORMAL NOISY.CASE MOUNT SOME BOLT MISSING.	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	LEATHER PORTION CRACK	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED,GET JERKING.	الحالة النظرية للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Indicator & Hazard light	HAZARD BUTTON SIGN LOGO MISSING	الاشارات
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Interior Condition		الحاله الداخليه
08.A Other	CENTER CONSOLE BOX COVER PORTION CUT , INTERIOR PARTS GETTING RUSTY/SIGN OF WATER FLOODED.	اخرى
08.B AC Condition	NOT COOLING , BOTH SIDE AC VENT ADJUSTABLE MISSING	المكيف
08.C Power Window Switch And Glass	FRONT RIGHT SIDE SWICTH DAMAGE	مفتاح النافذه و الزجاج
08.D Dash Board	GLOVE BOX PORTION WORN OUT	لوحة القيادة
08.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
09 Battery Condition		حالة البطارية
09.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae