

Queue Number 2591826

Transaction Date 29 Jul 2026, 15:31:34

Site Name
840 - Emirates AuctionsTransaction Number
88706795 (CC10021) (CC10011)

Vehicle Details

Chassis Number	5FNYF6872G*****
Specification	GCC Specification
Make	Honda
Model	Pilot
Model Year	2016
Color	Unknown
Mileage	465744 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	LEFT SIDE BOTH REPAIRED REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION GETTING RUSTY	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	PORTION GETTING RUSTY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Windshield	SPOT CRACK	زجاج
01.H Roof	REPAINTED PORTION REPAIRED,LEFT SIDE ROOF RAIL REPAIRED	السقف
01.I Bonnet	REPAIRED REPAINTED	غطاء المحرك
01.J Pillars	LEFT SIDE A/PILLAR OUTER PANEL REPAIRED	القوائم
01.K Trunk	REPAINTED PORTION REPAIRED	صندوق
01.L Door Handle & Lock	RIGHT SIDE BOTH OUTER DOOR HANDLE PART MISSING	مقابض الأبواب والأقفال
01.M Vehicle Color	GREY	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

Condition	Remarks	الحالة
03.A Engine Visual Condition	PARTS GETTING RUSTY,OIL LEAK	الحالة النظرية للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	PARTS GETTING RUSTY,MINOR JERKING	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
06.B Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
06.C Revers Light	NOT WORKING	نور الرجوع للخلف
07 Steering Condition		المقود
07.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
08 Interior Condition		الحالة الداخليه
08.A Other	CENTER CUP HOLDER PANEL DAMAGED	اخرى
08.B Mirror	COVER DAMAGED	المرايا
08.C AC Condition	NO COOLING	المكيف
08.D Roof Light	FRONT PANEL LOOSE	أنارة السقف
08.E Audio	NOT WORKING	صوتيات
08.F Dash Board	PORTION LOOSE	لوحة القيادة
08.G Steering Wheel and control buttons	WORN OUT,HORN NOT WORKING	عجلة القيادة وازرار التحكم
08.H Gear Shifting Lever	KNOB WORN OUT,PANEL DAMAGED	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on

للشكاوي والمقترحات يمكنك التواصل معنا عبر

