




TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Jul 2022, 13:16:15
Transaction Number	87609987 (CC10006)	Queue Number	312309



Chassis Number	WBAFG4107AL347575
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	X6 - 35
Model Year	2010
Color	Black
Mileage	004131 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Doors	PORTION REPAIRED,REPAINTED	أبواب
01.B Fenders	FRONT BOTH SIDE BLASTIC PAINT CANNOT CHECK & REAR RIGHT SIDE PORTION REPAIRED REPAINTED	مدكار
01.C Bonnet	SHOCK WEAK	غطاء المحرك
01.D Bumper	GRAIL LOOSE	دعامية
01.E Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
02 Engine Condition		المحرك
02.A Visual Engine Condition	SIGN OF LEAK	حالة المحرك النظري
03 Interior Condition		الحاله الداخليه
03.A Audio	REAR BOTH SIDE STERIO COVER DAMAGED	صوتيات
03.B Roof Ceiling	PORTION LOOSE	بطانه السقف
03.C AC Condition	OK , REAR GRILL PORTION DAMAGED & COOLENT PIPE OIL LEAK	المكيف
03.D Sunroof	NOT WORKING	فتحت سقف
03.E Other	REAR LEFT SIDE CURTAIN DAMAGED	اخرى

DEFECT	REMARKS	
04 Steering Condition		المقود
04.A Steering Oil	OIL LEAK	زيت المقود
04.B Axle	BOOT CUT	اكسلات
05 Brake Condition		الفرامل
05.A Hand Brake	NOT WORKING	فرامل اليد
06 Chassis Condition		الشاسي
06.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
07 Transmission Condition		الجير
07.A Road Test	NOT CHECK	فحص علي الطريق
08 Tires and Rims Condition		الاطارات
08.A Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
08.B Front Tyre	BOTH SIDE 2022	الاطار الامامي
09 Lights		الاضاءة
09.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.