



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	25 Sep 2022, 16:23:27
Transaction Number	29218232 (CC10006)	Queue Number	594823



Chassis Number	JMYLRV95WEJ711741
Engine Number	
Vehicle Class	Car
Manufacturer	Mitsubishi
Model	Pajero
Model Year	2014
Color	Grey
Mileage	183559 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Transmission Condition</b>		الجير
01.A Visual Gear Box Condition	NOT SHIFTING.	حالة الجير النظري
01.B Road Test	NOT CHECKED.	فحص علي الطريق
<b>02 Interior Condition</b>		الحاله الداخليه
02.A AC Condition	NOT COOLING	المكيف
<b>03 Body</b>		جسم المركبة
03.A Trunk	REPAINTED,NOT OPEN	صندوق
03.B Fenders	FRONT LEFT SIDE , REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
03.C Doors	FRONT LEFT SIDE PORTION REPAIRED,REPAINTED	أبواب
03.D Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
03.E Bumper	MISALIGN	دعامية
03.F Bonnet	REPAINTED	غطاء المحرك
03.G Rusty	UNDER BODY PARTS GETTING RUSTY.	صدأ
<b>04 Suspension System</b>		ممتص الصدمات

DEFECT	REMARKS	
04.A Shock Absorber	LEAK	ممتص الصدمات
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Front Tyre	BOTH SIDE 2018 & CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
<b>06 Lights</b>		<b>الاضاءة</b>
06.A Head Light	LENS FADED	الاضاءة الرئيسية
06.B Tail Light	LEFT SIDE COVER BROKEN.	الانارة
<b>07 Chassis Condition</b>		<b>الشاصي</b>
07.A Chassis	CHECKED VISIBLE AREA OK.	الشاسيه
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Steering Boot	CUT.	ربلة المقود
<b>09 Engine Condition</b>		<b>المحرك</b>
09.A Visual Engine Condition	MINOR OIL LEAK.	حالة المحرك النظري
09.B Mount	MOUNT BUSHES CRACK.	كرسي
<b>10 Seats Condition</b>		<b>المقاعد</b>
10.A Seat Condition	PORTION DAMAGE	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.