

TEST CERTIFICATE

Site Number
Transaction Number

04.A Visual Engine Condition

840-Emirates Auctions 77741156 (CC10008) Transaction Date

22 Jun 2022, 13:47:51

حالة المحرك النظرى

Queue Number

312309

Car

Chassis Number

JTMHT05J094022968

Engine Number

Vehicle Class

Manufacturer Toyota

Model Land Cruiser

Model Year 2009

Color White

Mileage **173416 Km**

Fuel Type Petrol

No. Of Cylinders

Specification GCC Specification



DEFECT REMARKS

| O1 Body | | جسم المركبة |
|----------------------|------------------------------------------------------------------------|--------------|
| 01.A Fenders | REAR BOTH SIDE FENDER REPAINTED.PORTION REPAIRED&FRONT FENDER REFITTED | مدكار |
| 01.B Bonnet | REFITTED | غطاء المحرك |
| 01.C Floor | RIGHT SIDE MIDDILE BODY MOUNT RUSTY MINOR HOLE | الارضية |
| 01.D Rusty | UNDER BODY PARTS, SUSPENSION ,CHASSIS GETTING RUSTY | صدأ |
| 01.E Paint | BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT, SCRATCHES | الصبغ |
| 01.F Doors | FRONT RIGHT SIDE REPAINTED | أبواب |
| 02 Chassis Condition | | الشاصي |
| 02.A Chassis | OK/GETTING MINOR RUSTY | الشاسيه |
| 03 Suspension System | | ممتص الصدمات |
| 03.A Arms | FRONT LOWER ARM BUSHES WORN OUT | ازرع |
| 03.B Shock Absorber | REAR RIGHT SIDE OIL LEAK | ممتص الصدمات |
| 04 Engine Condition | | المحرك |

OIL WET, REFITTED

| DEFECT | REMARKS | |
|-----------------------------------|----------------------------------------|-------------------|
| 05 Transmission Condition | | الجير |
| 05.A Visual Gear Box Condition | REFITTED | حالة الجير النظرى |
| 05.B Road Test | NOT CHECK | فحص علي الطريق |
| 06 Interior Condition | | الحاله الداخليه |
| 06.A AC Condition | OK&CENTER GRILL BROKEN | المكيف |
| 07 Tires and Rims Condition | | الاطارات |
| 07.A Front Tyre | LEFT SIDE 2016 EXPIRED&RIGHT SIDE 2019 | الاطار الامامي |
| 07.B Rear Tyre | LEFT SIDE 2016 EXPIRED&RIGHT SIDE 2019 | الاطار الخلفي |
| 08 Steering Condition | | المقود |
| 08.A Steering Oil | OIL LEAK | زيت المقود |
| 08.B Steering Boot | BOOT LOOSE | ربلة المقود |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.