

Queue Number 2852646

Transaction Date 10 Oct 2026, 12:45:25

Site Name
840 - Emirates AuctionsTransaction Number
76866364 (CC10013) (CC10025)

Vehicle Details

Chassis Number 5KBRL688XK*****
Specification GCC Specification
Make Honda
Model Odyssey
Model Year 2019
Color White
Mileage 110230 Km
Fuel Type Petrol
Transmission Type
No. Of Cylinders 6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DENT DIRTY	الارضية
01.F Bumper	MISALIGN , PORTION CRACK	دعامية
01.G Trunk	REPAINTED PORTION REPAIRED , NOT WORKING PROPERLY	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK DRIPPING , COMPONENTS REFITTED , PARTS GETTING RUSTY , DIRTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Exhaust System

نظام العادم

04.A Other	DENT	اخرى
------------	------	------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	OIL LEAK , COMPONENTS REFITTED , PARTS GETTING RUSTY , DIRTY	الحالة النظرية للجير
--------------------------------	--	----------------------

05.B Road Test	NOT CHECKED	فحص علي الطريق
----------------	-------------	----------------

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	SIGN OF LEAK	ممتص الصدمات
07.B Arms	ARM BUSHES DRY CRACK	ازرع
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B AC Condition	OK	المكيف
09.C Roof Light	REAR NOT WORKING	أنارة السقف
09.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae