CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2479538
Transaction Date	27 Jun 2026, 22:03:36
Site Name	840 - Emirates Auctions
Transaction Number	43194165 (CC10006) (CC10019)



Vehicle Details

Chassis Number	WDDUG8GB7J*******
Specification	GCC Specification
Make	Mercedes
Model	S 560
Model Year	2018
Color	Silver
Mileage	117494 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY STICKER PAINT NOT CHECKED ,STICKER PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS, SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,MUDDY, CHECKED ONLY VISIBLE AREA	الارضية
01.E Bumper	MISALIGN, PORTION DAMAGED	دعامية
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FULLY COVERD, CHECKED VISIBLE AREA ONLY OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	SHAKING, REFITTED MINOR LEAK . PARTS RUSTY .	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	GEAR NOT SHIFTING , REFITTED OIL LEAK . PARTS RUSTY .	الحالة النظريه للجير
04.B Gear Box Mount	BUSH CRACKED	كرسي الجير
04.C Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 CRACKED	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2023 CRACKED	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
06.B Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CRACKED	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CRACKED	مؤخرة الرودات
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخري
09.B AC Condition	NORMAL COOLING	المكيف
09.C Power Window Switch And Glass	FRONT RIGHT SIDE NOT WORKING	مفتاح النافذه و الزجاج
09.D Dash Board	PORTION LOOSE MELTED	لوحة القياده
09.E Door Panel	PORTION LOOSE	لوحة بطانة الباب
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae