



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Sep 2022, 17:31:21
Transaction Number	50573124 (CC10006)	Queue Number	597605



Chassis Number	5FNRL6H25KB089219
Engine Number	
Vehicle Class	Car
Manufacturer	Honda
Model	Odyssey
Model Year	2019
Color	Silver
Mileage	34320 Miles
Fuel Type	Petrol
No. Of Cylinders	6
Specification	USA Imported

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Air Bag	DAMAGED	وسائد هوائية
01.B AC Condition	OK	المكيف
01.C Other	LEFT SIDE INNER PILLAR COVER LOOSE	اخرى
02 Body		جسم المركبة
02.A Door Handle &Lock	REAR LEFT SIDE AUTO DOOR NOT FULL OPENING .	مقابض الأبواب والأقفال
02.B Floor	SPARE WHEEL HOUSING DENT	الارضيه
02.C Pillars	LEFT SIDE PILLARS ROCKER PANEL REPAIRED.	القوائم
02.D Fenders	LEFT SIDE BOTH FENDER REPAINTED,PORTION REPAIRED	مدكار
02.E Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
02.F Doors	LEFT SIDE BOTH DOOR REPAIRED ,REPAINTED& RIGHT SIDE REPAINTED,PORTION REPAIRED	أبواب
02.G Trunk	PORTION REPAIRED,REPAINTED	صندوق
02.H Sign of side accident		وجود مؤشر لحادث في الجانب
03 Engine Condition		المحرك
03.A Visual Engine Condition	OIL WET ,REFITTED	حالة المحرك النظري

DEFECT	REMARKS	
03.B Other	UNDER COVER LOOSE.	اخرى
04 Transmission Condition		الجير
04.A Visual Gear Box Condition	OIL LEAK,REFITTED	حالة الجير النظري
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 20219 CRACKED,	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
06 Steering Condition		المقود
06.A Steering Oil	OIL LEAK	زيت المقود
07 Exhaust System		نظام العادم
07.A Other	CATALYTIC CONVERTER OPEN REWELDED	اخرى
08 Chassis Condition		الشاسي
08.A Chassis	CHECKED ONLY VISBLE AREA OK.	الشاسيه
09 Lights		الاضاءة
09.A Tail Light	FRONT RIGHT SIDE PARK LIGHT NOT WORK.RIGHT SIDE COVER MISALIGN.	الانارة
10 Brake Condition		الفرامل
10.A Brake Pedal	BRAKE PADEL SPONGY	دواسة الفرامل

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.