



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 Jan 2023, 12:56:27
Transaction Number	59695039 (CC10006)	Queue Number	657682



Chassis Number	1FMCU9DG0CKB60168
Engine Number	
Vehicle Class	Car
Manufacturer	Ford
Model	Escape
Model Year	2012
Color	--
Mileage	308220 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Body</b>		جسم المركبة
01.A Bumper	SCRATCHES,MISALIGN.	دعامية
01.B Roof	RUSTY HOLE WEAK	السقف
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Vehicle Color	GOLDEN.	لون المركبة
01.E Sign of back accident		وجود مؤشر لحادث في الخلف
01.F Other	BACK PANEL,QUARTER PANEL ,COMPARTMENT FLOOR REPAIRED.	اخرى
01.G Paint	BODY PORTION REPAIRED REPAINTED ,DENTS SCRATCHES ,RUSTY FADED	الصبغ
<b>02 Tires and Rims Condition</b>		الاطارات
02.A Rear Tyre	BOTH SIDE 2019 CRACKED .	الاطار الخلفي
02.B Front Tyre	BOTH SIDE 2018/2016 EXPIRED ,CRACKED .	الاطار الامامي
<b>03 Suspension System</b>		ممتص الصدمات
03.A Shock Absorber	LEAK WEAK	ممتص الصدمات
03.B Arms	LOWER ARM BUSHES CUT,	ازرع
03.C Suspension Subframe	RUSTY HOLE WEAK.	

DEFECT	REMARKS	
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Visual Gear Box Condition	REFITTED OIL LEAK.	حالة الجير النظري
04.B Road Test	NOT CHECKED.	فحص علي الطريق
<b>05 Seats Condition</b>		<b>المقاعد</b>
05.A Seat Condition	DAMAGE.	حالة المقاعد
<b>06 Chassis Condition</b>		<b>الشاسي</b>
06.A Chassis	REAR BOTH SIDE CHASSIS REPAIRED ,DENT ,	الشاسيه
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	REFITTED OIL LEAK.	حالة المحرك النظري
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Head Light	LENS FADED.	الاضاءة الرئيسية
08.B Indicator & Hazard light	REAR LEFT NOT WORKING.	الاشارات
<b>09 Interior Condition</b>		<b>الحاله الداخليه</b>
09.A AC Condition	LOW COOLING.	المكيف
09.B Steering Wheel and control buttons	WORN OUT.	عجلة القيادة وازرار التحكم

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.