



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **24 May 2023, 10:09:34**  
 Transaction Number **40123250 (CC10010)** Queue Number **720356**



Chassis Number **6T1BF9FK4EX530569**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Toyota**  
 Model **Camry**  
 Model Year **2014**  
 Color **--**  
 Mileage **001 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **4**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	NOT CHECKED.	المكيف
01.B Steering Wheel and control buttons	WORN OUT,PORTION DAMAGE.	عجلة القيادة وازرار التحكم
01.C Dash Board	CRACKED ,PORTION DAMAGE .	لوحة القيادة
<b>02 Lights</b>		<b>الاضاءة</b>
02.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Sign of back accident		وجود مؤشر لحادث في الخلف
03.B Floor	PORTION DENT .	الارضيه
03.C Vehicle Color	VIOLET BIEGE	لون المركبة
03.D Sign of front accident		وجود مؤشر لحادث في المقدمة
03.E Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY	صدأ
03.F Other	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED. BACK PANEL ,BUMPER FRAME ,QUARTER PANEL REPAIRED.	اخرى
03.G Paint	BODY PORTION REPAIRED ,PORTION REPAINTED ,DENTS SCRATCHES ,PORTION FADED ,PORTION RUSTY,STICKER DAMAGE ,TAXI.	الصبغ

DEFECT	REMARKS	
03.H Bumper	MISALIGN ,PORTION DAMAGE.	دعامية
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Front Tyre	BOTH SIDE 2019/2018 EXPIRED ,CRACKED .	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2018/2019 EXPIRED ,CRACKED .	الاطار الخلفي
<b>05 Steering Condition</b>		<b>المقود</b>
05.A Steering Boot	CUT ,	ربلة المقود
05.B Axle	BOOT CUT .	اكسلات
05.C Steering Box	OIL LEAK .	جهاز المقود
<b>06 Transmission Condition</b>		<b>الجير</b>
06.A Visual Gear Box Condition	NOT CHECKED ,REFITTED OIL LEAK.	حالة الجير النظري
06.B Road Test	NOT CHECKED .	فحص علي الطريق
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Arms	LOWER ARM BUSHES CRACKED .	ازرع
07.B Shock Absorber	WEAK ,LEAK .	ممتص الصدمات
<b>08 Chassis Condition</b>		<b>الشاسي</b>
08.A Chassis	CHECKED ONLY VISIBLE AREA OK.	الشاسيه
<b>09 Engine Condition</b>		<b>المحرك</b>
09.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,REFITTED .OIL LEAK.PARTS MISSING .	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.