



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	25 Sep 2022, 10:23:27
Transaction Number	62047695 (CC10009)	Queue Number	595673



Chassis Number	WBAFR1101DDX83992
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	530
Model Year	2013
Color	White
Mileage	76350 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Roof Ceiling	LOOSE	بطانه السقف
01.B AC Condition	OK	المكيف
01.C Door Panel	FRONT LEFT SIDE PORTION MELTED	لوحة بطانة الباب
01.D Audio	SCREEN PORTION FADED	صوتيات
01.E Power Window Switch	REAR BOTH SIDE CARTAIN MISSING	مفتاح النافذه
02 Body		جسم المركبة
02.A Fenders	PORTION REPAIRED REPAINTED	مدكار
02.B Windshield	REAR CARTAIN NOT WORKING	زجاج
02.C Floor	UNDER FLOOR FENDER CHASSIS FULLY COVERED CHECKED VISIBLE AREA, COVER PORTION DAMAGED	الارضية
02.D Trunk	PORTION REPAIRED REPAINTED & AUTO NOT WORKING	صندوق
02.E Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
02.F Sign of side accident		وجود مؤشر لحادث في الجانب
03 Transmission Condition		الجير
03.A Visual Gear Box Condition	MINOR OIL LEAK REFITTED	حالة الجير النظري

DEFECT	REMARKS	
03.B Road Test	NOT CHECK	فحص علي الطريق
03.C Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
04 Suspension System		ممتص الصدمات
04.A Other	STABLIZER LINK BOOT CUT	اخرى
04.B Arms	LOWER ARM BUSHES CUT	ازرع
04.C Ball Joint	BOOT CUT	مفصل كروي
05 Steering Condition		المقود
05.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
06 Seats Condition		المقاعد
06.A Seat Condition	FRONT BOTH SIDE BACK COVER LOOSE	حالة المقاعد
07 Engine Condition		المحرك
07.A Smoke	MINOR WHITE SMOKE	دخان
07.B Visual Engine Condition	MINOR OIL LEAK REFITTED	حالة المحرك النظري
07.C Mount	MOUNT RUBBER CUT	كرسي
08 Tires and Rims Condition		الاطارات
08.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
09 Chassis Condition		الشاسي
09.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.