

Queue Number 2408781

Transaction Date 25 May 2026, 10:56:45

Site Name
840 - Emirates AuctionsTransaction Number
80327865 (CC10006) (CC10019)

Vehicle Details

Chassis Number	5XYPGDA52G*****
Specification	Imported
Make	Kia
Model	Sorento
Model Year	2016
Color	Red
Mileage	150329 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE REPAINTED, PORTION REPAIRED,	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES,PORTION FADED	الصبغ
01.C Doors	FRONT LEFT SIDE REPAINTED, PORTION REPAIRED,	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERD, CHECKED VISIBLE AREA ONLY	الارضية
01.F Bumper	MISALIGN,PORTION CRACKED	دعامية
01.G Bonnet	REPAINTED, PORTION REPAIRED, SHOCK WEAK	غطاء المحرك
01.H Other	FRONT BUMPER FRAME , FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT ,CROSS MEMBER REPAIRED	اخرى

02 Chassis Condition

الشاسي

02.A Chassis	COVERD ,CHECKED VISIBLE AREA ONLY OK	الشاسيه
--------------	--------------------------------------	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED, SHAKING, MINOR LEAK, PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	JERKING, REFITTED, PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACKED	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
06.B Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
06.C Brake Light	RIGHT SIDE NOT WORKING	نور الفرامل
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CUT	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED	اخرى
08.B Mirror	CENTER MIRROR DAMAGED,MISSING	المرآيا
08.C AC Condition	OK	المكيف
08.D Power Window Switch And Glass	FRONT RIGHT SIDE NOT WORKING	مفتاح النافذه و الزجاج
08.E Dash Board	PORTION CRACKED	لوحة القيادة

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae