



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 Jan 2022, 18:14:52
Transaction Number	98865235 (CC10006)	Queue Number	312309



Chassis Number	6T1BF9FKODX424036
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Camry
Model Year	2013
Color	Silver
Mileage	211923 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT & REAR FENDER REPAINTED, PORTION REPAIRED & FRONT BOTH FENDER REFITTED, PORTION RUSTY	مدكار
01.B Doors	RIGHT SIDE BOTH DOOR REPAINTED, PORTION REPAIRED	أبواب
01.C Trunk	REPAINTED	صندوق
01.D Bumper	REPAINTED	دعامة
01.E Rusty	UNDER BODY PARTS, SUSPENSION GETTING MINOR RUSTY	صدأ
01.F Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT, SCRATCHE, PAINT PORTION FADED	الصبغ
01.G Bonnet	REPAINTED, PORTION REPAIRED, REFITTED & OPENING HANDLE DAMAGED	غطاء المحرك
02 Chassis Condition		الشاسي
02.A Chassis	OK	الشاسيه
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Gear Box	OK	الجير
04 Seats Condition		المقاعد

DEFECT	REMARKS	
04.A Seat Belt	OK	حزام الأمان
04.B Seat Condition	SEAT HAVE EXTRA COVER,DIRTY & FRONT RIGHT SIDE SEAT COVER DAMAGED	حالة المقاعد
05 Wipers and Arms		المساحات
05.A Wiper Arm &Blade	WORNOUT,RUSTY	ازرع المساحات والشفرات
06 Suspension System		ممتص الصدمات
06.A Arms	FRONT LOWER ARM BUSHES MINOR CRACKED	ازرع
07 Brake Condition		الفرامل
07.A Break Pads	GETTING WEAR	سفايف الرامل
07.B Disc&Drum	GETTING RUSTY	دسك ووطنابير الفرامل
08 Interior Condition		الحاله الداخليه
08.A Mirror	LEFT SIDE MIRROR LOOSE	المرايا
08.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.C Power Window Switch	FRONT LEFT SIDE NOT WORKING	مفتاح النافذه
08.D AC Condition	OK	المكيف
08.E Other	GEAR SHIFTING LEVER KNOB WORN OUT	اخرى
09 Tires and Rims Condition		الاطارات
09.A Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
09.B Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED , AIR PRESSOR LOW	الاطار الامامي
09.C Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED , AIR PRESSOR LOW	الاطار الخلفي
10 Lights		الاضاءة
10.A Revers Light	NOT WORKING	نور الرجوع للخلف
10.B Head Light	LENS FADED&BOTH LOW BEAM NOT WORKING	الاضاءة الرئيسية
11 Battery Condition		حالة البطارية
11.A Battery Condition	NOT WORKING	حالة البطارية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.