



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 18 Nov 2022, 11:31:52 |
| Transaction Number | 46548923 (CC10009) | Queue Number | 625712 |



| | |
|------------------|--------------------------|
| Chassis Number | JN8AY2NY2E9067536 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Nissan |
| Model | Patrol |
| Model Year | 2014 |
| Color | Grey |
| Mileage | 399783 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 8 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|---|--|----------------------------|
| 01 Body | | جسم المركبة |
| 01.A Paint | BODY PORTION REPAINTED & MINOR DENTS, SCRATCHES | الصبغ |
| 01.B Fenders | FRONT REFITTED | مدكار |
| 01.C Other | FRONT BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED | اخرى |
| 01.D Bonnet | REFITTED | غطاء المحرك |
| 01.E Sign of front accident | | وجود مؤشر لحادث في المقدمة |
| 02 Interior Condition | | الحالة الداخلية |
| 02.A AC Condition | OK | المكيف |
| 02.B Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |
| 03 Engine Condition | | المحرك |
| 03.A Mount | MOUNT CRACK | كرسي |
| 03.B Visual Engine Condition | MINOR OIL LEAK | حالة المحرك النظرى |
| 04 Transmission Condition | | الجير |
| 04.A Gear Box Mount | MOUNT CRACK | كرسي الجير |
| 04.B Road Test | NOT CHECK | فحص علي الطريق |

| DEFECT | REMARKS | |
|------------------------------------|---|---------------------|
| 04.C Visual Gear Box Condition | SIGN OF MINOR OIL LEAK | حالة الجير النظري |
| 05 Suspension System | | ممتص الصدمات |
| 05.A Arms | LOWER ARM BUSHES CRACKED | ازرع |
| 05.B Ball Joint | BOOT CUT | مفصل كروي |
| 06 Steering Condition | | المقود |
| 06.A Tie Rod End | BOOT CUT | مؤخرة الرودادات |
| 06.B Axle | BOOT CUT | اكسلات |
| 06.C Steering Boot | BOOT CUT | ربلة المقود |
| 06.D Steering Oil | MINOR OIL LEAK | زيت المقود |
| 07 Lights | | الاضاءة |
| 07.A Warning Light | WARNING LIGHT ON IN DISPLAY | ضوء تحذير |
| 08 Tires and Rims Condition | | الاطارات |
| 08.A Front Tyre | BOTH SIDE 2019 CRACKED , | الاطار الامامي |
| 08.B Rear Tyre | BOTH SIDE 2019 CRACKED , | الاطار الخلفي |
| 09 Chassis Condition | | الشاسي |
| 09.A Chassis | FRONT BOTH SIDE CHASSIS REPAIRED , LEFT SIDE CHASSIS BEND | الشاسيه |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Registration



RTA

✓ PASS

| | |
|--------------------------|--------------------------|
| Plate Details : | 2 34305 Sharjah Private |
| Chassis No : | JN8AY2NY2E9067536 |
| Vehicle Make : | NISSAN |
| Vehicle Model : | PATROL |
| Vehicle Class : | Light Vehicle |
| Body Type : | STATION |
| Fuel : | Benzene |
| Color : | Gray |
| Drive Direction : | -- |
| Dimensions : (H x W x L) | -- x -- x -- |
| Current Odometer : | 399825 Kms. |
| Origin : Japan | Model Year : 2014 |
| Gear Type : Automatic | Engine Size : 3500 CC |
| Engine No : VK56107792A | Horse Power : 400 |
| Axles No : 2 | Cylinders : 8 |
| No Of Doors : 4 | No Of Seats : 8 |
| G. V. W. : 2650 Kgs. | Empty Weight : 2000 Kgs. |

| | | | |
|---------------------------|---------------------|--------------|-------|
| Certificate Number : | 5-TAS-2022-18164226 | | |
| Inspection Date : | 23-11-2022 | | |
| Certificate Print Date : | 23-11-2022 | | |
| Services : | Registration Test | | |
| Vehicle Testing Partner : | Tasjeel | | |
| Vehicle Testing Center : | Tasjeel Al Barsha | | |
| Total Time Taken : | 3 min 12 sec | | |
| Appointment Ref Number : | -- | | |
| Start Time : | 16:38 | End Time : | 16:41 |
| Lane : | 01 | Token No. : | 338 |
| Attempt : | 2 | Prints No. : | 1 |

Carbon footprint



Take action to protect Dubai environment

Estimated Vehicle Consumption (Rate in 12 Months)

| | | | |
|-------------------|------------------------|--------------------|---------------------------|
| | | | |
| 36347 KM | 3740 L | 12754 AED | 9.0 ton |
| Distance per year | Fuel consumed per year | Fuel cost per year | Carbon footprint per year |

Inspection Findings

Discrepancies

| Discrepancies | Old Value | New Value | Verified |
|--|-----------|-----------|----------|
| Engine Size Discrepancy in Engine Size | 3500 | 5600 | |

Inspection Remarks:

FRONT FENDER FRAME AND BULK HEAD REPAIRED, LEFT SIDE CHASSIS FRAME HEATED REPAIRED. HAVE PASS CCM REPORT.

Payment Details

| | | | |
|----------------------------------|-----------------------------------|--------------------------------|--|
| Inspection Performed by 36294 | Payment Method Cash | Transaction Number 18164226 | Service Fees AED 70 Collected on 23/11/2022 |
| Parking Slot No -- | Service Name Registration Test | Attempt 2 | Received by Abdulraouf Yousuf |

- ① This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.
② Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

