



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>10 Oct 2021, 17:42:49</b>
Transaction Number	<b>17996779 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>1B7HF16Z2TS598260</b>
Engine Number	
Vehicle Class	<b>Heavy</b>
Manufacturer	<b>Dodge</b>
Model	<b>Ram</b>
Model Year	<b>1996</b>
Color	<b>Antique white</b>
Mileage	<b>331844 N/A</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	PORTION REPAIRED & REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Doors	PORTION REPAIRED, REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS ,FLOORING , CHASSIS, SUSPENTION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR RUST PROOFED & BODY LEVEL HIGH	الارضية
01.F Bumper	REPAINTED	دعامية
01.G Roof	REPAINTED	السقف
01.H Bonnet	REPAIRED & REPAINTED	غطاء المحرك
01.I Other	FRONT FENDER FRAME, BUMPER FRAME , RADITOR SUPPORT REPAIRED	اخرى
<b>02 Chassis Condition</b>		<b>الشاسي</b>
02.A Chassis	CHASSIS FRAME COMPLETELY THICK RUST PROOFED	الشاسية
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Other	OIL LEAK	اخرى
03.B Mount	BUSHES CRACKED	كرسي
<b>04 Seats Condition</b>		<b>المقاعد</b>
04.A Other	RIGHT SIDE SEAT BELT NOT WORKING	اخرى

DEFECT	REMARKS	
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Gear Box	OIL LEAK & GEAR SHAFT NOT WORKING PROPERLY	الجير
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Front Tyre	BOHT 2020 & MODIFIED	الاطار الامامي
06.B Rear Tyre	BOHT 2020 & MODIFIED	الاطار الخلفي
<b>07 Wipers and Arms</b>		<b>المساحات</b>
07.A Other	WORN OUT	اخرى
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Head Light	OK	الاضاءة الرئيسية
08.B Other	OK	اخرى
<b>09 Brake Condition</b>		<b>الفرامل</b>
09.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
<b>10 Suspension System</b>		<b>ممتص الصدمات</b>
10.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED	ازرع
10.B Shock Absorber	LEAK	ممتص الصدمات
10.C Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	
10.D Other	SUSPENTION COMPLETELY RUST PROOFED	اخرى
<b>11 Steering Condition</b>		<b>المقود</b>
11.A Steering Box	OIL LEAK	جهاز المقود
11.B Tie Rod End	BUSHES CUT	مؤخرة الرودادات
11.C Other	STABILIZER LINK & CONTROL BAR BUSHES CUT	اخرى
<b>12 Interior Condition</b>		<b>الاجزاء الداخلية</b>
12.A Other	DASH BOARD DAMAGED & ALL INNER COVER DAMAGED , HRON NOT WORKING	اخرى
12.B Mirror	OK	المرايا
12.C AC Condition	NOT WORKING	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.