



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	27 Sep 2022, 17:12:33
Transaction Number	69436969 (CC10009)	Queue Number	597012



Chassis Number	WDDHF5GB3AA218165
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	E 350
Model Year	2010
Color	Grey
Mileage	97632 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Engine Condition		
		المحرك
01.A Visual Engine Condition	SHAKING/SIGN OF MINOR OIL LEAK	حالة المحرك النظري
01.B Other	AIR INTAK PIPE DAMAGED	اخرى
02 Transmission Condition		
		الجير
02.A Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
02.B Visual Gear Box Condition	JERKING	حالة الجير النظري
02.C Road Test	NOT CHECK	فحص علي الطريق
03 Body		
		جسم المركبة
03.A Bonnet	REFITTED	غطاء المحرك
03.B Bumper	MISALIGN	دعامية
03.C Floor	UNDER FLOOR FENDER CHASSIS FULLY COVERED CHECKED VISIBLE AREA	الارضية
03.D Fenders	REAR LEFT SIDE PORTION REPAIRED REPAINTED & FRONT RIGHT SIDE REFITTED	مدكار
03.E Sign of side accident		وجود مؤشر لحادث في الجانب
03.F Doors	LEFT SIDE BOTH PORTION REPAIRED,REPAINTED	أبواب
03.G Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR	الصبغ

DEFECT	REMARKS	
	DENT,SCRATCHES	
04 Lights		الاضاءة
04.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
05 Interior Condition		الحالة الداخليه
05.A AC Condition	OK	المكيف
05.B Power Window Switch	FRONT LEFT SIDE SWITCH BUTTON MISSING	مفتاح النافذه
05.C Roof Ceiling	PORTION LOOSE	بطانه السقف
05.D Mirror	LEFT SIDE FOLDING NOT WORKING PROPERLY	المرايا
06 Suspension System		ممتص الصدمات
06.A Arms	LOWER ARM BUSHES CUT	ازرع
06.B Ball Joint	BOOT CUT	مفصل كروي
06.C Other	STABLIZER LINK BOOT CUT	اخرى
07 Steering Condition		المقود
07.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
08 Seats Condition		المقاعد
08.A Seat Condition	PORTION CRACKED	حالة المقاعد
09 Tires and Rims Condition		الاطارات
09.A Rims Condition	SCRATCHES	حالة الجنوط
09.B Front Tyre	BOTH SIDE 2021	الاطار الامامي
09.C Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
10 Chassis Condition		الشاصي
10.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.