

Queue Number 2830316

Transaction Date 03 Oct 2026, 13:00:05

Site Name
840 - Emirates AuctionsTransaction Number
37692447 (CC10013) (CC10025)

Vehicle Details

Chassis Number	JTDBV42E3C*****
Specification	GCC Specification
Make	Toyota
Model	Corolla
Model Year	2012
Color	White
Mileage	372397 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE & FRONT LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED DENTS SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED , REAR LEFT SIDE BEADING MISSING	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION DIRTY DENT	الارضية
01.F Bumper	MISALIGN PORTION LOOSE	دعامية
01.G Bonnet	SWITH HANDLE LOOSE	غطاء المحرك
01.H Trunk	REPAINTEDN PORTION REPAIRED , REFITTED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	FRONT RIGHT CHASSIS OUTER SKIRT OPEN DETACH / MUDDY / CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK , MUDDY , DIRTY , COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	EXTRA COVER	حالة المقاعد
---------------------	-------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MUDDY DIRTY , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED , RIGHT SIDE CRACK	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE CRACK	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	ARM BUSHES DRY CRACK	ازرع
08.C Ball Joint	BOOT CUT	مفصل كروي
08.D Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
10 Interior Condition		الحالة الداخليه
10.A Other	CENTER CONSOLE BOX WORN OUT LOCK COVER PORTION DAMAGED (INTERIOR PARTS GETTING RUSTY) SIGN OF FLOODED	اخرى
10.B Mirror	ADJUSTMENT NOT WORKING	المرايا
10.C AC Condition	OK , GRILL ADJUSTMENT PORTION MISSING	المكيف
10.D Audio	COVER PANEL PORTION DAMAGED	صوتيات
10.E Dash Board	PORION DAMAGED , MELTED	لوحة القيادة
10.F Roof Ceiling	LEFT SIDE GRAB HANDLE MISSING	بطانه السقف
10.G Sun Visor	LEFI SIDE GLASS MIRROR MISSING	حاجب الشمس
10.H Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.I Steering Wheel and control buttons	WORN OUT , HORN NOT WORKING	عجلة القيادة وازرار التحكم
10.J Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص

only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae