



## TEST CERTIFICATE

|                    |                              |                  |                              |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number        | <b>840-Emirates Auctions</b> | Transaction Date | <b>22 Jul 2022, 11:20:10</b> |
| Transaction Number | <b>53621192 (CC10006)</b>    | Queue Number     | <b>312309</b>                |



|                  |                          |
|------------------|--------------------------|
| Chassis Number   | <b>1FM5K8B85EGB21537</b> |
| Engine Number    |                          |
| Vehicle Class    | <b>Car</b>               |
| Manufacturer     | <b>Ford</b>              |
| Model            | <b>Explorer</b>          |
| Model Year       | <b>2014</b>              |
| Color            | <b>Blue</b>              |
| Mileage          | <b>197529 Km</b>         |
| Fuel Type        | <b>Petrol</b>            |
| No. Of Cylinders | <b>6</b>                 |
| Specification    | <b>GCC Specification</b> |

| DEFECT                             | REMARKS  |                        |
|------------------------------------|--|------------------------|
| <b>01 Body</b>                     |  | <b>جسم المركبة</b>     |
| 01.A Trunk                         | NOT OPEN FOR CHECK                                     | صندوق                  |
| 01.B Paint                         | PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY | الصبغ                  |
| 01.C Floor                         | FLOORING DENT & OPEN DETACHED                          | الارضية                |
| 01.D Rusty                         | UNDER BODY PARTS GETTING RUSTY                         | صدأ                    |
| <b>02 Interior Condition</b>       |  | <b>الحاله الداخليه</b> |
| 02.A Dash Board                    | INNER BOX DAMAGED                                      | لوحة القيادة           |
| 02.B AC Condition                  | NOT COOLING  | المكيف                 |
| 02.C Door Panel                    | PORTION DAMAGED & LOOSE                                | لوحة بطانة الباب       |
| 02.D Other                         | GEAR SHIFTING LEVER DUST COVER LOOSE                   | اخرى                   |
| <b>03 Lights</b>                   |  | <b>الاضاءة</b>         |
| 03.A Warning Light                 | WARNING LIGHT ON IN DISPLAY                            | ضوء تحذير              |
| <b>04 Tires and Rims Condition</b> |  | <b>الاطارات</b>        |
| 04.A Front Tyre                    | BOTH SIDE 2017 EXPIRED , CRACKED                       | الاطار الامامي         |
| 04.B Rear Tyre                     | BOTH SIDE 2017 EXPIRED , CRACKED                       | الاطار الخلفي          |

| DEFECT                           | REMARKS                  |                    |
|----------------------------------|--------------------------|--------------------|
| <b>05 Transmission Condition</b> |                          | <b>الجير</b>       |
| 05.A Visual Gear Box Condition   | OK                       | حالة الجير النظرى  |
| 05.B Road Test                   | NOT CHECK                | فحص علي الطريق     |
| <b>06 Engine Condition</b>       |                          | <b>المحرك</b>      |
| 06.A Visual Engine Condition     | OK                       | حالة المحرك النظرى |
| <b>07 Chassis Condition</b>      |                          | <b>الشاسي</b>      |
| 07.A Chassis                     | OK                       | الشاسيه            |
| <b>08 Steering Condition</b>     |                          | <b>المقود</b>      |
| 08.A Other                       | STABILIZER LINK BOOT CUT | اخرى               |
| 08.B Tie Rod End                 | BOOT CUT                 | مؤخرة الروداد      |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.