



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>06 Oct 2021, 09:36:19</b>
Transaction Number	<b>91091249 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JTMBD33V0A5256004</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>RAV 4</b>
Model Year	<b>2010</b>
Color	<b>White</b>
Mileage	<b>0 N/A</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Paint	TOTALY BODY REPAINTED&PORTION REPAIRED	الصبغ
01.B Rusty	UNDER BODY PART CHASSIS,FLOOR GETTING RUSTY	صدأ
01.C Fenders	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED&FENDER REFITED	مدكار
01.D Bonnet	REFITIED	غطاء المحرك
01.E Bumper	REAR BUMPER FRAME RUSTY	دعامة
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Other	OIL LEAK&REFITIED	اخرى
<b>03 Suspension System</b>		<b>ممتص الصدمات</b>
03.A Suspension Subframe	FRONT CROSS MEMBER REPAIRED&RIGHT SUPPORT BRACKET ONE BOLT MISSING	
<b>04 Lights</b>		<b>الاضاءة</b>
04.A Head Light	RIGHT HEAD LIGHT BRACKET BROKEN	الاضاءة الرئيسية
<b>05 Seats Condition</b>		<b>المقاعد</b>
05.A Other	REAR SEATS HAVE HOLE	اخرى
<b>06 Wipers and Arms</b>		<b>المساحات</b>
06.A Other	WORN OUT	اخرى
<b>07 Steering Condition</b>		<b>المقود</b>

DEFECT	REMARKS	
07.A Axle	FRONT LEFT OUTER AXLE BOOT GREASE LEAK	اكسلات
07.B Steering Oil	MINOR OIL LEAK	زيت المقود
<b>08 Transmission Condition</b>		<b>الجير</b>
08.A Gear Box	REFFITED&SHIFTING CABLE NOT FIX PROPRLY	الجير
<b>09 Interior Condition</b>		<b>الاجزاء الداخلية</b>
09.A AC Condition	OK&AC GRILL FRAME BROKEN	المكيف
09.B Other	RIGHT CONSOLE BOX COVER CRACKED	اخرى
<b>10 Chassis Condition</b>		<b>الشاسي</b>
10.A Chassis	OK	الشاسيه
<b>11 Tires and Rims Condition</b>		<b>الاطارات</b>
11.A Front Tyre	BOTH SIDE 2016/2014 CRACKED & EXPIRED	الاطار الامامي
11.B Rear Tyre	BOTH SIDE 2016 CRACKED & EXPIRED	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.