

Queue Number

2850014

Transaction Date

09 Oct 2026, 16:37:31

Site Name

840 - Emirates Auctions

Transaction Number

62916530 (CC10013) (CC10011)



Vehicle Details

Chassis Number	WD4WG2A90G*****
Specification	GCC Specification
Make	Mercedes
Model	V 250
Model Year	2016
Color	Black
Mileage	394139 Km
Fuel Type	Diesel
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR RIGHT SIDE PORTION REPAIRED REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION DIRTY MINOR DENT	الارضية
01.E Bumper	MISALIGN,MINOR DENT SCRATCHES	دعامية
01.F Windshield	SPOT DENT	زجاج
01.G Bonnet	REFITTED,STAY SHOCK NOT WORKING	غطاء المحرك
01.H Trunk	AUTO NOT WORKING,INNER PANEL COVER PART MISSING,PORTION REPAINTED	صندوق
01.I Door Handle & Lock	LEFT SIDE SLIDING DOOR REAR SWITCH FADED	مقابض الأبواب والأقفال
01.J Fuel Tank	DENT	خزان الوقود

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS PORTION COVERED CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Smoke	MINOR BLACK	دخان
03.B Engine Visual Condition	OIL WET , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Propeller Shaft	FLANGE RUBBER DRY CRACK	ناقل الحركة
04.C Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
05.C Rims Condition	DENTS SCRATCHES	حالة الجنوط

06 Lights

الاضاءة

06.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
-----------------	--------------------	------------------

07 Suspension System

ممتص الصدمات

07.A Shock Absorber	LEAK	ممتص الصدمات
---------------------	------	--------------

08 Interior Condition

الحالة الداخليه

08.A Other	INTERIOR PORTION MODIFIED REFITTED GETTING RUSTY,REAR TABLE TRAY PANEL PORTION DAMAGED	اخرى
08.B Mirror	CENTER VIEW MIRROR BACK COVER LOOSE	المرايا
08.C AC Condition	OK,GRILL PORTION LOOSE	المكيف
08.D Audio	TOUCHPAD MINOR SCRATCHES	صوتيات
08.E Sun Visor	BOTH SIDE MIRROR CASE COVER DAMAGED	حاجب الشمس
08.F Door Panel	PORTION WORN OUT LOOSE	لوحة بطانة الباب
08.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae