

Queue Number

2902262

Transaction Date

24 Oct 2026, 11:35:29

Site Name

840 - Emirates Auctions

Transaction Number

37636725 (CC10009) (CC10012)



Vehicle Details

Chassis Number	WBAYE8105E*****
Specification	GCC Specification
Make	BMW
Model	750LI
Model Year	2014
Color	Black
Mileage	149889 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.F Bumper	MISALIGN	دعامية

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Chassis Number	CHASSIS NUMBER STICKER LOOSE	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---------------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	FRONT RIGHT SIDE SEAT BACK COVER LOOSE , REAR PORTION CUT	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	REFITTED GETTING RUSTY MINOR JERKING	الحالة النظرية للجير
--------------------------------	--------------------------------------	----------------------

05.B Road Test	NOT CHECKED	فحص علي الطريق
----------------	-------------	----------------

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.B Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE FADED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Other	SUSPENSION REFITTED	اخرى
08.C Ball Joint	BOOT CUT	مفصل كروي
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
10 Interior Condition		الحالة الداخلية
10.A Mirror	LEFT SIDE FOLDING NOT WORKING , LOOSE	المرآيا
10.B AC Condition	OK	المكيف
10.C Power Window Switch And Glass	REAR LEFT SIDE CURTAIN NOT WORKING	مفتاح النافذه و الزجاج
10.D Audio	SCREEN , REAR BOTH SIDE L C D GETTING FADED	صوتيات
10.E Dash Board	LEATHER REPLACED	لوحة القيادة
10.F Roof Ceiling	PORTION LOOSE	بطانه السقف
10.G Door Panel	WORN OUT , PORTION MELTED , LEATHER REPLACED , PORTION LOOSE	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae