CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2977946
Transaction Date	12 Nov 2026, 12:06:20
Site Name	840 - Emirates Auctions
Transaction Number	14828033 (CC10008) (CC10011)



Vehicle Details

Chassis Number	KL1GM5EU8E*******
Specification	GCC Specification
Make	Chevrolet
Model	Malibu
Model Year	2014
Color	Grey
Mileage	120356 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE,REAR RIGHT REPAINTED PORTION REPAIRED,FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,DENTS SCRATCHES	الصبغ
01.C Doors	FRONT LEFT SIDE REPAINTED,REAR LEFT DAMAGED & RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN PORTION DAMAGED	دعامية
01.F Bonnet	REPAINTED PORTION REPAIRED,REFITTED	غطاء المحرك
01.G Pillars	RIGHT SIDE C/PILLAR OUTER PANEL REPAIRED	القوائم
01.H Sign of front accident		وجود مؤشر لحادث في المقدمة
01.I Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Mount	CRACK	كرسي
03.B Other	ENGINE OIL CAP DAMAGED NOT FIXED	اخري
03.C Engine Visual Condition	MINOR OIL LEAK ,PARTS GETTING RUSTY ,REFITTED	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	PORTION DAMAGED WORN OUT,FRONT BOTH SEAT MINOR LOOSE,LEFT SIDE COVER PORTION CRACKED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS GETTING RUSTY ,REFITTED	الحالة النظريه للجير
05.B Gear Box Mount	CRACK	كرسي الجير
05.C Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025 WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	SWITCH PANEL WORN OUT,LENS FADED,LEFT SIDE PORTION DAMAGED WASHER MISSING	الاضاءة الرئيسية
07.B Tail Light	PORTION FADED,LEFT SIDE PORTION DAMAGED	الضوء الخلفي
07.C Fog light	LEFT SIDE CHROME COVER MISSING	كشاف الضباب
08 Brake Condition		الفرامل
08.A Hand Brake	SWITCH WORN OUT	فرامل اليد
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARST GETTING MINOR RUSTY, SIGN OF FLOODED,CENTER CONSOLE BOX COVER MINOR WORN OUT PANEL PORTION CRACK	اخري
10.B Mirror	RIGHT SIDE LOOSE AUTO FOLDING NOT WORKING	المرايا
10.C AC Condition	NO COOLING,GRILL CHROME PANEL PORTION CRACK	المكيف
10.D Power Window Switch And Glass	SWITCH PORTION FADED	مفتاح النافذه و الزجاج
10.E Audio	LCD LOCK SWITCH WORN OUT	صوتيات
10.F Dash Board	PORTION WORN OUT LOOSE	لوحة القياده
10.G Roof Ceiling	PORTION LOOSE	بطانه السقف
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص

only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**