

Queue Number

2905937

Transaction Date

26 Oct 2026, 16:33:47

Site Name

840 - Emirates Auctions

Transaction Number

85160634 (CC10013) (CC10019)



Vehicle Details

Chassis Number	WDB1400511*****
Specification	Imported
Make	Mercedes
Model	S 500
Model Year	1998
Color	Blue
Mileage	229878 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY TOTALY REPAINTED PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION RUSTY	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR RUST PROOFED MINOR DENT	الارضية
01.D Bumper	MISALIGN	دعامية
01.E Windshield	FRONT SPOT CRACKED	زجاج
01.F Vehicle Model	S500L	طراز المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS MUDDY DIRTY PORTION GETTING RUSTY / CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK , REFITTED , ABNORMAL NOISY , PARTS GETTING RUSTY , MISFIRING , OIL PAN DENT	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
---------------------	-----------------	--------------


05 Exhaust System

نظام العادم

05.A Modification	EXHAUST SYSTEM MODIFIED	تعديلات
-------------------	-------------------------	---------

06 Transmission Condition

الجير



Condition	Remarks	الحالة
06.A Gear Box Visual Condition	REFITTED , MINOR JERKING , PARTS GETTING RUSTY	الحالة النظرية للجير
06.B Propeller Shaft	FLANCE RUBBER DRY CRACK	ناقل الحركة
06.C Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	RIGHT SIDE MINOR CRACK	الاضاءة الرئيسية
09 Suspension System		مفتص الصدمات
09.A Suspension Subframe	DENT	مفصل كروي
09.B Ball Joint	UPPER BOOT CRACK	
10 Steering Condition		المقود
10.A Steering Oil	OIL LEAK DRIPPING	زيت المقود
11 Interior Condition		الحالة الداخلية
11.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED & CENTER CONSOLE BOX LOCK DAMAGED	اخرى
11.B Mirror	BOTH SIDE ADJUSTMENT & FOLDING NOT WORKING LOOSE & CENTER MIRROR COVER CRACKED	المرايا
11.C AC Condition	NOT COOLING	المكيف
11.D Roof Light	REPAIRED.PORION LOOSE	أنارة السقف
11.E Power Window Switch And Glass	RIGHT SIDE BOTH NOT WORKING	مفتاح النافذه و الزجاج
11.F Dash Board	PORION CRACKED	لوحة القيادة
11.G Door Panel	PORION DAMAGED,LOOSE	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB WORN OUT,MELTED	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae